

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga	Located In:	Corner Code #
(County)		
1. Public Land Survey	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S 18 T 48N R 32W _____	15
	S 18 T 48N R 32W _____	1
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat _____		
5. Private Claims		

Register of Deeds Stamp & File Number

1	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5	⊙												
6	18		17		16		15		14		13		
7	⊙												
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 15 05/30/2012 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(15-Sec. 18) West 1/16 corner between Sections 18 and 19. Not previously monumented. The Government plat of this townships gives a distance of 35.61 chains from A7 to B7.

(1-Sec. 18) West 1/16 corner between Sections 7 and 18. Not previously monumented. The Government plat of this township gives a distance of 35.30 chains between A5 and B5.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(15-Sec. 18) Established the position for the corner at 20 chains, proportionate to the original record, west of Quarter corner B7, on the Section line between B7 1324.05' east and Section corner A7 1033.43' west.

(1-Sec. 18) Established the position for the corner at 20 chains, proportionate to the original record, west of Quarter corner B5, and on the Section line between B5 1325.00' east and Section corner A5 1013.63' west.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(15) Set 1"IDx32" I.pipe with 4" alum. MDNR cap. Set measuring nail with MDNR tag in the side of:
 11" W.Pine S68E 4.4' mrkd "1/16S BT"
 14" W.Pine S14W 17.5' do
 9" Spruce S83W 13.15' do
 18" W.Pine N31W 9.15' do
 Set sq'd cedar post adjacent.
 Bearings are magnetic.

(1) Set 1"IDx32" I.pipe with 4" alum. MDNR cap. Set measuring nail with MDNR tag in the side of:
 5" Spruce N18E 7.25' mrkd "1/16S BT"
 4" Spruce S84E 20.6' do
 6" Balsam S63E 30.5' do
 4" Balsam S50W 14.15' do
 Set sq'd cedar post adjacent.
 Bearings are magnetic.

Signed by Stephan J. Szyszkoski
 Surveyor's Michigan License No. 33986

Date 09/12/2012



For the Michigan Department of Natural Resources, Forest Resources Division