

SURVEY & REMONUMENTATION

FEB 21 2001

SECTION

**LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970**

MARQUETTE COUNTY
MICHIGAN
RECEIVED FOR RECORD

2000 DEC 22 AM 10:17

Patricia A. Mosley
REGISTER OF DEEDS

For corners in
MARQUETTE
(County)

Located In:

Corner Code #

- | | | | |
|------------------------------------|-------|---------------------------|-------------|
| 1. Public Land Survey | | T <u>49N</u> R <u>26W</u> | <u>B-13</u> |
| | | T ___ R ___ | ___ |
| | | T ___ R ___ | ___ |
| | | T ___ R ___ | ___ |
| 2. Property Controlling in Section | S ___ | T ___ R ___ | ___ |
| | S ___ | T ___ R ___ | ___ |
| 3. Miscellaneous Property in Sec. | S ___ | T ___ R ___ | ___ |
| | S ___ | T ___ R ___ | ___ |

LIBER **R2** PAGE **272**
Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, GERALD W. CARLSON, in a field survey on October 19 th, 2000, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

1	A	B	C	D	E	F	G	H	I	J	K	L
2		6		5		4		3		2		1
3												
4		7		8		9		10		11		12
5												
6		18		17		16		15		14		13
7												
8		19		20		21		22		23		24
9												
10		30		29		28		27		26		25
11												
12		31		32		33		34		35		36
13												

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:
B-13: South Quarter Corner of Section 31, T49N-R26W.
1844: Austin Burt's original Township Line survey notes of T49N-R26W, describe the corner monument as a wood post referenced by:
10" Sugar N62E, 73 links 16" B. Oak N18W, 51 links

No subsequent record evidence recovered.

**RATIFIED BY PEER GROUP
P.A. 345 OF 1990**

Larry J. Bugeme
DATE 11/6/00

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
B-13: 2000: SCA survey crews conducted a thorough search of the area and found no evidence of monumentation except a blue paint line. Corner position was established by proportionate measurement on line between the SW corner of Section 31 and the Southeast corner of Section 31.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
B-13: 2000: Set a 5/8" x 19" rebar 3 1/4" diameter aluminum tablet Marquette County Survey Monument stamped to identify the corner. Monument is 0.8' above ground. Monument is drilled and grouted into bedrock. Referenced by:
6" Maple S12E, 22.21' 10" Maple S83E, 22.82'
9" Maple N44E, 18.18' 6" Maple N11W, 11.33'
North 1/4 Corner Section 6, T48N-R26W S89°38'47"W, 13.74'
Green Steel Sign Post w/ Yellow Survey Marker Sign N10E, 3.62'
Distance East 2618.33', distance West 2423.26'.
Note: Bearing trees have painted face, butt, and side nail blazes, d.h. measuring nails, and stamped B.T. Tags affixed.
Bk. 15, Pg. 49 T49N-R26W Corner Search Sheet 2000035



Signed by Gerald W. Carlson Date 12-19-00