


MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION



LAND CORNER RECORD

T. 51 NR 28 W.

Marquette

COUNTY

DESCRIPTION OF CORNER 1/4 corner between sections 19 and 20

DESCRIPTION OF CORNER MONUMENT pyramid of rocks

WITNESSES TO CORNER 12" Hemlock - N 38 W - 26 Links

12" Cedar - N 49 E - 15 Links

24" Cedar - S 30 E - 60 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR
RESTORED.

Corner was found, and later shown to me by Mr. Harold Cole, Engineer
and Cruiser for Northwestern Veneer and Plywood Corp., who are logging a large
area in this township.

Both B.T.'s still visible, but in very poor condition. Because of the
rocky ground, we were unable to place our regular corner marker, and were forced
to place a pyramid of rocks for the corner.

Corner placed and witnessed September 14, 1950

SURVEYORS SEAL

SIGNED Dean C. DeLaMater
REGISTERED LAND SURVEYOR

DATE 9/29/50