

**SURVEY &
REMONUMENTATION**
APR 11 1995
COMMISSION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
MENOMINEE
(County)

Located In:

Corner Code #

- | | | | | | |
|------------------------------------|---|-----|---|-----|------|
| 1. Public Land Survey | T | 32N | R | 27W | C-08 |
| | T | | R | | |
| | T | | R | | |
| | T | | R | | |
| 2. Property Controlling in Section | S | | T | R | |
| | S | | T | R | |
| 3. Miscellaneous Property in Sec. | S | | T | R | |
| | S | | T | R | |

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

William Lenca

Dec. 06 94

I, _____, in a field survey on _____, 19____, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- 1847: Original Survey by James H. Mullett - B.T.'s - W. Pine, 10", S64°W, 14 lks; Maple, 8", N57°E, 13 lks. No original evidence for this corner was recovered.
- 1884: Survey by Orson Burlingame, surveyor, shows this corner in relation to other corners in the S1/2 of Section 20. No corner description or B.T.'s are given.
- 1970: Recorded Plat of "GLEN ACRES SUBDIVISION" by George B. Wilson, RLS No. 17607, shows a tie to this corner and describes it in the legend as a 4" dia. concrete monument 36" long.
- 1973: Certified Survey No. 24 by George B. Wilson, RLS No. 17607, shows a tie to this corner and describes it in the legend as a 4" round concrete monument with 1/2" dia. iron pin.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

We found a 4 inch diameter concret monument with a 1/2 inch diameter iron pin at an ancient fence corner. Fences run East - West and South from this location. There is another North - South fence 16 feet West of this location. The monument fits recorded distances to other survey corners from Certified Surveys mentioned in part "A". Burlingame's distance of 2691 feet to the SW Corner of Section 20 fits closely with Wilson's measurement of 2682.8 feet. We accepted the concrete monument as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 2-1/2" x 30" Alum. Pipe/3-1/4" dia. Alum. Cap stamped for corner in place of concrete monument:

8" dia. Maple	N83°E	38.04 feet	Scr. NBT
7" dia. Maple	S03°E	44.77 feet	Scr. NBT
2" dia. Iron Pipe	N87°W	15.85 feet	
12" dia. Maple	N02°W	19.10 feet	Scr. NBT
Survey Sign Post	West	1.2 feet	

NOTE: All bearings are magnetic bearings. All distances are measured with steel tape. Distances to trees are to nail in side of tree.

Signed by William Lenca Date Dec. 07, 1994
Surveyor's Michigan License No. 26461

Approved by Menominee County
Land Survey Remonumentation
Four Group Under Act 345 of
P.A. of 1988 On DEC 16 1994
McDermis RLS
ACTING Chairman
RECEIVED FOR RECORD
94 DEC 27 AM 10:4
PAGE # 200 BK-9
BARBARA MORRISON
REGISTER OF DEEDS
MENOMINEE MI 49858
Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19	20		21		22		23		24			
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

