

# SURVEY & REMONUMENTATION

FEB 11 1998

Approved by Menominee County  
Lead Survey Remonumentation  
Four Group Under Act 345 Of  
P.A. of 1998 On 10/31 199 2  
McDawn RLS  
Chairman

## SECTION

For corners in

MENOMINEE

(County)

Located In:

Corner Code #

1. Public Land Survey

T2N R 28W

1/3-5

T R

(005)

T R

T R

2. Property Controlling in Section

S T R

S T R

3. Miscellaneous

S T R

Property in Sec.

S T R

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_

5. Private Claims \_\_\_\_\_

I, William Lenca, in a field survey on Mar. 26, 19 97 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below.

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

A	B	C	D	E	F	G	H	I	J	K	L	M
1												
2	6	5	4	3	2	1						
3												
4	7	8	9	10	11	12						
5												
6	18	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

A. Description of original monument and accessories and/or subsequent restoration:

1848: Original Survey by James H. Mullett - B.T.'s - Hemlock, 10" - S34°W - 17 lks.; W. Pine, 18" - N74°E - 18 lks. All evidence of the original corner or its accessories have been destroyed by shore erosion.

1982: CERTIFIED SURVEY No. 296, recorded by George B. Wilson, RLS No. 17607, shows a retracement of the South Line of Section 11, 32/28 between the S1/4 Corner and the Menominee River. An existing Iron Pipe near the Menominee River and an original line tree 1104 feet to the East were used to control the direction of this line.

1982: CERTIFIED SURVEY No. 330 recorded by, George B. Wilson, RLS No. 17607 shows concrete monuments placed along the South Line of Section 11, 32/28 at the W1/16 on the South Line and at a point 508.34' West of the W1/16.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

We retraced the South Line of Section 11, T32N-R28W from the S1/4 Corner West to the Menominee River and found concrete monuments in place at the S1/4 Corner, at the W1/16 on the South Line of said Section 11 (1319.80 feet West of the S1/4 Corner) and at a point 508.34 feet West of the W1/16 Corner. The iron pipe shown as 57.81 feet West of this last monument was not recovered, however a 1-1/2" diameter iron pipe was found at the shore of the Menominee River and in line with the above monumentation. The measured distance from the S1/4 Corner to the existing iron pipe is 1972.38 feet compared to a GLO distance of 2030 feet. We accepted the position of the existing iron pipe as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 2" dia. Aluminum Pipe/3-1/4" dia. Alum cap stamped for corner location:

6" dia. Oak	N28°E	26.91 feet	Scr. NBT
Concrete Monument	East	144.20 feet	
SW Corner of Residence	S25°E	26.51 feet	
5/8" x 24" Iron Rod/2" dia. Alum. cap marked "WITNESS MARKER"	S38°W	11.52 feet	
Metal Survey Sign Post	N47°W	1.7 feet	

NOTE: All bearings are magnetic bearings. All distances are measured with steel tape. Distances to trees are to nail in side of tree.

Signed by William Lenca  
Surveyor's Michigan License No. 26461

Date Apr. 10, 1997

