

SURVEY & REMONUMENTATION

JAN 09 2001

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Approved by Menominee County
Land Survey Remonumentation
Peer Group Under Act 345 of
P.A. Of 1990 On 12/22, 2000
Mike Davis RLS
Chairman

For corners in

MENOMINEE
(County)

Located In:

Corner Code #

- | | | | | |
|------------------------------------|---|-------------|-------------|-----|
| 1. Public Land Survey | T | <u>33</u> N | <u>26</u> W | C-6 |
| | T | | R | |
| | T | | R | |
| | T | | R | |
| | T | | R | |
| 2. Property Controlling in Section | S | | T | R |
| | S | | T | R |
| 3. Miscellaneous Property in Sec. | S | | T | R |
| | S | | T | R |

BR 6 Pg. 206

RECEIVED FOR RECORD
28 DEC 2000 2:31:31 PM
BARBARA MORRISON
REGISTER OF DEEDS
MENOMINEE, MI 49858

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, William Lenca, in a field survey on Oct., 1900 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A	B	C	D	E	F	G	H	I	J	K	L
1											
2	6		5		4		3		2		1
3											
4	7		8		9		10		11		12
5											
6	18		17		16		15		14		13
7											
8	19		20		21		22		23		24
9											
10	30		29		28		27		26		25
11											
12	31		32		33		34		35		36

A. Description of original monument and accessories and/or subsequent restoration:

- 1848: Original Survey by James H. Mullett - B.T.'s - Fir, 10" - N35°E - 14 lks.; Fir, 8" - N45°W - 15 lks.; All original evidence or this corner has been destroyed by County Road improvements.
1987: L.C.R.C. No. 771, Book 3, by William Lenca, RLS No. 26461, states set Deep-1 Magnet in centerline of east-west county road and in line with an ancient fence line to the north. TIES: Nail in 8" White Birch, Scr. B.T., N20°W, 47.70', Nail in Power Pole, N55°E, 42.40', Nail in 9" White Birch, Scr. B.T., S09°E, 35.47', 3/4" dia. Iron, South, 30.36'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

The Deep-1 magnet set in 1987 has been destroyed by county road re-construction. We replaced the corner position from the ties in place per L.C.R.C. 771 (see part A). This position falls in the centerline of an East-West county road and in line with an ancient fence line to the North, fits the distance to the 1/4 Corner 1 mile east and the Section Corner 1/2 mile south per C.S. #340, and is accepted as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 5/8" x 24" Iron Rod/3-1/4" dia. Alum. cap stamped for corner location in Monument Box:

7" dia. Cedar	N54°E	92.84 feet	Scr. NBT
7" dia. Elm	S60°E	69.79 feet	Scr. NBT
3/4" dia. Iron Rod	South	30.41 feet	
11" dia. Cedar	N15°W	46.34 feet	Scr. NBT
Metal Survey Sign Post	South	31.6 feet	

NOTE: All bearings are magnetic bearings. All distances are measured with steel tape. Distances to trees are to nail in side of tree.

Signed by William Lenca
Surveyor's Michigan License No. 26461

Date Dec. 13, 2000

