

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

Approved by Menominee County
Land Survey Remonumentation
Peer Group Under Act 345 Of

P.A. Of 1990 On 12/16 19996

For corners in

MENOMINEE
(County)

Located in:

Corner Code #

1. Public Land Survey

T33N R27W B03

2. Property Controlling
in Section

S T R

3. Miscellaneous
Property in Sec.

S T R

4. Lot No. , Recorded Plat

5. Private Claims

I, William Lenca, in a field survey on Jun. 05, 1996 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1847: Original Survey by John Mullett - B.T.'s - Cedar, 4" - S44°E - 06 lks; Cedar, 6" - N21°W - 12 lks. All original evidence for this corner has been destroyed by county road improvements.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

We set this corner on a straight line between the SW Corner (A-3) and the SE Corner (C-3) of Section 6, T33N-R27W, and at a proportional distance between these two corners. The measured distance between these corners is 5185.29 feet compared to the GLO record distance of 5174.4 feet. We therefore set the S1/4 Corner (B-3) at a distance of 2645.57 feet West of the SE Corner (C-3) and accepted this location as a careful and faithful reestablishment of the position of the original corner. The corner position falls in the centerline of an east - west county road.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
Set 5/8" x 24" Iron Rod/3-1/4" dia. Alum. cap stamped for corner location:

12" dia. Cedar	N33°E	45.68 feet	Scr. NBT
8" dia. Cedar	S52°E	49.80 feet	Scr. NBT
5/8" x 24" Iron Rod/2" dia. Alum. cap marked "WITNESS MARKER"	S02°W	25.01 feet	
9" dia. Cedar	N34°W	57.12 feet	Scr. NBT
Metal Survey Sign Post	S02°W	25.5 feet	

NOTE: All bearings are magnetic bearings. All distances are measured with steel tape. Distances to trees are to nail in side of tree.

Signed by William Lenca
Surveyor's Michigan License No. 26461

Date Nov. 18, 1996

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2													
3													
4													
5													
6													
7													
8													
9													
10													
11													
12													
13													

