

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Menominee (County)	Located In:	Corner Code #
1. Public Land Survey	T _____ R _____ T _____ R _____ T _____ R _____	_____
2. Property Controlling in Section	S 13 T 34N R 29W S 12 T 34N R 29W S _____ T _____ R _____	3 10 _____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____ S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, Jeremy J. Pipp, in a field survey on 3/22/2012AD do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(03) North One-Sixteenth corner common to Sections 13 and 14. Not set in original
survey, no evidence of subsequent establishment.

(10) South One-Sixteenth corner common to Sections 12 and 13. Not set in original
survey, Found Capped Rebar (PS#26461) and Chest Blazed trees facing position.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(03) Corner position established by record measurement along a line extended from the
Northwest corner of Section 13 to the Meander Corner on the West line of Section 13.
Note: Found Angle Iron S61W +/-17' from monumented position.

(10) Corner position calculated mid-point and on-line between the East One-Quarter
corner and the Northeast corner of Section 3. Found Capped Rebar checked well for
position was accepted. Set MDNR monument over the top of said existing monument.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(03) DNR monument
8" Ash S88E 45.85' (1/16S,BT)
5" Ash S31E 13.29' (1/16S,BT)
7" Ash S48W 20.15' (1/16S,BT)
6" Ash N48W 23.93' (1/16S,BT)

All trees are blazed, scribed, and
painted. Measurements are to nail in
side of tree, bearings are magnetic.

(10) DNR monument
4" Ash N38E 15.15' (1/16S,BT)
8" Red Maple S43E 28.68' (1/16S,BT)
16" White Pine S62W 44.89' (1/16S,BT)
16" White Pine N57W 25.78' (1/16S,BT)

All trees are blazed, scribed, and
painted. Measurements are to nail in
side of tree, bearings are magnetic.

Signed by _____
Surveyor's Michigan License No. _____ 50447

For the Michigan Department of Natural Resources, Office of Land and Facilities

JEREMY J. Pipp

July 16, 2012

PROFESSIONAL

FORM NO. 10-1
APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971

20047

20041

Revised May 14, 1975

Revised Jan., 1983

Revised Oct., 1995