## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Menominee (County)	_ Located In:	Corner Code #			
1. Public Land Survey	T 34N R 29W T R	MC E of G03[003]			
2. Property Controlling in Section	S T R S T R				
3. Miscellaneous Property in Sec.	S T R S T R		Register of Deeds Stamp & File Number		
4. Lot No. , Red 5. Private Claims	corded Plat		1 A B C D E F G H I J K L N 2 6 5 4 3 2 1 1		
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with 7 the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, 8					
re-established, monumented, recove			9 10 30 29 28 27 26 25 11 12 31 32 33 34 35 36		

A. Description of original monument and accessories and/or subsequent restoration:

(MC E of GO3)[003] Meander Corner common to Sections 3 and 10 on left bank of Menominee River. 1852: Francis Coleman, DS. Set meander post witnessed by: Hickory 6 N40E 41 links (27.06'); Sugar 12 S40W 32 links (21.12'); 1928: Plat of Menominee Forest Estates #1, depicts a monumented position for the Section line between Sections 3 & 10.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(MC E of GO3)[OO3] No evidence of original survey. Re-established position using plat monuments found at Stations 60+00, 42+00 (bent), 30+19.8, 26+30.5, & Conc mon NW lot 47 (no station listed) according to the the Plat of Menominee Forest Estates #1. Position(s) fall in water and unstable slope; monumented 62.31 feet East of calculated Meander Corner position & 17.55 Feet East of Plat Corner position. Position is accepted as a careful and faithful WITNESS TO the position of the original corner AND Position is accepted as a careful and faithful WITNESS TO the Plat Corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(MC E of G03)[003]	DNR monu	ment			
7" Ash \$89E	57.02'	(MC,NBT)			
12" Maple S01W	8.66'	(MC, NBT)	OF MICH		
6" Ash N87W	13.47'	(MC,NBT)	A Linear Wall of the Control of the		
9" Ash N13E	29.00'	(MC,NBT)	**************************************		
All trees are blazed,	scribed,	painted,	JEREMY J.		
and signed. Measurements are to nail in PROFESSIONAL O					
side of tree, bearings are magnetic. A This SURVEYOR I					
metal rail & sign were set East 1.5 feet. No. 50447					
Signed by	- leve	my 6 de	Dates		
Surveyor's Michigan License No.	1	50447	ESSION		

July 17, 2012

For the Michigan Department of Natural Resources, Forest Resources Division