

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Menominee (County)	Located In:	Corner Code #
1. Public Land Survey	T 34N R 29W	MC S of G03
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

Register of Deeds Stamp & File Number

1	A	B	C	D	E	F	G	H	I	J	K	L	M
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, Jeremy J. Pipp, in a field survey on 4/04/2012AD do hereby state  
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2  
above were in conformance with regulations and rules therefore as required in the current manual of survey  
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of  
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with  
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,  
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded  
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(MC S of G03) Meander Corner common to Sections 9 and 10 on left bank of Escanaba River.  
1852: Francis Coleman, DS. Set meander post witnessed by: Sugar 10 N46E ## links (##');  
Sugar 10 S43W 8 links (5.28').

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(MC S of G03) No evidence of original survey or subsequent restoration found. Corner  
position reestablished by extending a line North from the West One-Quarter corner of  
Section 10 along a line that is parallel with the East line of Section 10. GLO distance  
from the One-Quarter Section corner to this position is 37.24 Chains (2457.84 feet); this  
position falls in the water. Monumented witness position 2397.97 feet North of One-Quarter  
Corner and +/-35 Feet from the Waters Edge (along line). Position is accepted as a careful  
and faithful WITNESS TO the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(MC S of G03)	DNR monument
6" Ironwood	N45E 18.81' (MC,NBT)
8" Maple	N64E 4.96' (MC,NBT)
9" Oak	S15E 8.23' (MC,NBT)
5" Oak	S51W 23.63' (MC,NBT)

All trees are blazed, scribed, painted,  
and signed. Measurements are to nail in  
side of tree, bearings are magnetic. A  
metal rail & sign were set South 1.5  
feet.

Signed by

Surveyor's Michigan License No.

Jeremy J. Pipp  
50447



July 17, 2012

For the Michigan Department of Natural Resources, Office of Land and Facilities