

# SURVEY & REMONUMENTATION

FEB 11 1998

Approved by Menominee County  
Land Survey Remonumentation  
Four Group Under Act 345 Of

P.A. Of 1990 On 10/31, 199 2

McL. Davis RLS  
Chairman

## SECTION

For corners in

MENOMINEE

(County)

Located In:

Corner Code #

1. Public Land Survey

T4N R 27W

E/F-07

T R

(003)

T R

T R

2. Property Controlling  
in Section

S T R

S T R

3. Miscellaneous  
Property in Sec.

S T R

S T R

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_

5. Private Claims \_\_\_\_\_

I, William Lenca, in a field survey on June 25, 19 97 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2													
3													
4													
5													
6													
7													
8													
9													
10													
11													
12													
13													

A. Description of original monument and accessories and/or subsequent restoration:

- 1848: Original Survey by James H. Mullett - B.T.'s - Lynn, 10" - S87°E - 29 lks.; Ironwood, 4" - N54°E - 23 lks. All original evidence for this corner has been destroyed by ice shoves and shoreline erosion.
- 1928: Plat of SCHUETTE SUMMER RESORT recorded by A.L. Hillis shows monumentation of the South Line of Section 16 as it extends West to the Menominee River. A Meander Corner Monument is not described.
- 1971: Certified Survey No. 6 recorded by George B. Wilson, RLS No. 17607, shows ties to original plat monuments as they relate to other lot corners.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

We recovered the N1/4 Corner (F-7) of Section 16, as established and monumented in the plat of Schuette Summer Resort. We then recovered the NE Corner of Lot 1 of Certified Survey No. 6, said corner being shown as 33 feet South of the North Line of said Section 16, and established a point 33 feet North of this corner which would be a point on the North Line of Section 16. We extended this line West to the shore of the Menominee River and set the meander corner on the high bank of the Menominee River. Our measured distance from the Corner F-7 (N1/4 Corner Sec. 16) to Meander Corner E/F-7 is 1496.8 feet compared to the GLO distance of 1442.1 feet. We accepted this location as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:  
Set 2" dia. Aluminum Pipe/3-1/4" dia. Alum. cap stamped for corner location:

8" dia. Cedar	N22°E	7.20 feet	Scr. NBT
12" dia. Red Oak	S60°E	9.76 feet	Scr. NBT
8" dia. Maple	S24°W	20.78 feet	Scr. NBT
10" dia. Cedar	S73°W	22.94 feet	Scr. NBT
Survey Sign Post	S33°E	1.0 feet	
Menominee River Bank	West	6.0 feet	

NOTE: All bearings are magnetic bearings. All distances are measured with steel tape. Distances to trees are to nail in side of tree.

Signed by William Lenca  
Surveyor's Michigan License No. 26461

Oct. 07, 1997

Date

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971  
REVISED MAY 14, 1975  
REVISED JAN., 1983  
REVISED OCT., 1986

553

