

FEB 11 1998

Approved by Menominee County  
Land Survey Remonumentation  
Four Group Under Act 245 Of  
P.A. Of 1980 On 12/16 1997  
Mr. Lewis RLS  
Chairman

SECTION

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in  
MENOMINEE  
(County)

Located in: Corner Code #

1. Public Land Survey

T 34N R 27W (008) C-10/11  
T \_\_\_\_\_ R \_\_\_\_\_  
T \_\_\_\_\_ R \_\_\_\_\_  
T \_\_\_\_\_ R \_\_\_\_\_

2. Property Controlling  
in Section

S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_

3. Miscellaneous  
Property in Sec.

S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_

97 DEC 22 AM 11:28  
REGISTERED LAND SURVEYOR  
WILLIAM LENCA  
575 BLS  
Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

I, William Lenca, in a field survey on Nov. 26, 1997 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below.

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

- 1848: Original Survey by James H. Mullett - B.T.'s - Y. Pine, 18" - N85°W - 17 lks.; Y. Pine, 16" - N64°E - 21 lks. All original evidence for this corner has been destroyed by river erosion and ice jams.
- 1967: Plat of Survey by Robert Olsen shows he found an iron 346' North of the Southwest Corner of Section 29, T34N - R27W.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

We recovered an angle iron 346' North of the Southwest Corner of Section 29 on the bank of the Menominee River as indicated on Robert Olsen's Plat of Survey dated 1967. There are remnants of an ancient fence running North along this line from the existing concrete monument at the SW Corner as monumented in the Plat of Wallace Summer Resort. This corner monument has been used by local surveyors for many years, and is accepted as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 2" dia. Aluminum Pipe/3-1/4" dia. Alum cap stamped for corner location in place of existing iron:

6" dia. Cedar	N33°E	14.09 feet	Scr. NBT
7" dia. White Pine	S47°E	17.28 feet	Scr. NBT
18" dia. Oak	S20°W	27.27 feet	Scr. NBT
6" dia. Norway Pine	N78°W	10.57 feet	Scr. NBT
Metal Survey Sign Post	North	1.0 feet	
Menominee River	North	29 feet	

NOTE: All bearings are magnetic bearings. All distances are measured with steel tape. Distances to trees are to nail in side of tree.



Signed by William Lenca  
Surveyor's Michigan License No. 26461

Date Dec. 12, 1997

575