

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Menominee	Located In:	Corner Code #
(County)		
1. Public Land Survey	T R	
	T R	
	T R	
2. Property Controlling in Section	S 10 T 35N R 25W	2
	S 19 T 35N R 25W	13
	T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, Jeremy J. Pipp, in a field survey on 1/05/2012AD do hereby state
1/04/2012AD
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(02) East One-Sixteenth corner common to Sections 3 and 10. Not set in original survey, no evidence of subsequent establishment.

(13) Southeast One-Sixteenth corner of Section 19. Not set in original survey, no evidence of subsequent establishment.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(02) Corner position established mid-point and on-line between the North One-Quarter corner and the Northeast corner of Section 10.

(13) Corner position established at the intersection of the South and East One-Sixteenth lines of Section 19.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(02) DNR monument
10" Maple S72E 16.60' (1/16S,BT)
10" Twin Maple S12W 14.43' (1/16S,BT)
14" Y. Birch N73W 29.42' (1/16S,BT)
11" Cedar N04W 28.55' (1/16S,BT)

All trees are blazed, scribed, and painted. Measurements are to nail in side of tree, bearings are magnetic.

Signed by Jeremy J. Pipp
Surveyor's Michigan License No. 50447

(13) DNR monument
11" B. Spruce N17E 18.80' (1/16S,BT)
11" B. Spruce S47E 2.52' (1/16S,BT)
11" Tamarack S68E 24.75' (1/16S,BT)
11" Tamarack N52W 40.59' (1/16S,BT)

All trees are blazed, scribed, and painted. Measurements are to nail in side of tree, bearings are magnetic.

JEREMY J. PIPP
PROFESSIONAL SURVEYOR
Date July 16, 2012

For the Michigan Department of Natural Resources, Office of Land and Facilities

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971

Revised May 14, 1975

Revised Jan., 1983

Revised Oct., 1995