

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Menominee (County)	Located In:	Corner Code #
1. Public Land Survey	T R	
	T R	
	T R	
2. Property Controlling in Section	S 32 T 35N R 28W	8
	S 32 T 35N R 28W	11
	T R	
3. Miscellaneous Property in Sec.	S T	
	S T	
	T R	
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

Register of Deeds Stamp & File Number

1	A	B	C	D	E	F	G	H	I	J	K	L	M
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, Jeremy J. Pipp, in a field survey on 2/15/2012AD do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(08) Center-West One-Sixteenth corner of Section 32. Not set in original survey, no evidence of subsequent establishment.

(11) Southwest One-Sixteenth corner of Section 32. Not set in original survey, no evidence of subsequent establishment.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(08) Corner position established mid-point and on-line between the Center One-Quarter corner and the West One-Quarter corner of Section 32.

(11) Corner position established at the intersection of the South and West One-Sixteenth lines of Section 32.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(08) DNR monument
8" W. Birch N49E 12.69' (1/16S,BT)
11" W. Birch S74E 16.31' (1/16S,BT)
3" Spruce S09W 14.15' (1/16S,BT)
5" Poplar N73W 24.44' (1/16S,BT)

All trees are blazed, scribed, and painted. Measurements are to nail in side of tree, bearings are magnetic.

Signed by Jeremy J. Pipp
Surveyor's Michigan License No. 50447

(11) DNR monument
9" Sugar N52E 26.16' (1/16S,BT)
11" Basswood S42E 23.92' (1/16S,BT)
9" Sugar S55W 40.36' (1/16S,BT)
6" Ironwood N27W 22.13' (1/16S,BT)

All trees are blazed, scribed, and painted. Measurements are to nail in side of tree, bearings are magnetic.

JEREMY PIPP Date July 16, 2012
PROFESSIONAL SURVEYOR

For the Michigan Department of Natural Resources, Office of Land and Facilities

20029

20030

