

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Menominee (County)	Located In:	Corner Code #
1. Public Land Survey	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S 31 T 35N R 28W	11
	S 31 T 35N R 28W	12
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, Jeremy J. Pipp, in a field survey on 2/15/2012AD do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(11) Southwest One-Sixteenth corner of Section 31. Not set in original survey, no
evidence of subsequent establishment.

(12) Center-South One-Sixteenth corner of Section 31. Not set in original survey, no
evidence of subsequent establishment.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(11) Corner position established at the intersection of the South and West One-Sixteenth
lines of Section 31.

(12) Corner position established mid-point and on-line between the Center One-Quarter
corner and the South One-Quarter corner of Section 31.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(11) DNR monument
6" Maple N45E 93.75' (1/16S,BT)
21" Red Pine S19W 64.5' (1/16S,BT)
6" Maple S62W 83.7' (1/16S,BT)
7" Maple N24W 68.60' (1/16S,BT)

All trees are blazed, scribed, and
painted. Measurements are to nail in
side of tree, bearings are magnetic.

Signed by Jeremy J. Pipp
Surveyor's Michigan License No. 50447

(12) DNR monument
9" Oak N53E 28.85' (1/16S,BT)
22" Red Pine S69E 76.82' (1/16S,BT)
10" Red Maple S66W 22.55' (1/16S,BT)
15" Cedar N52W 56.24' (1/16S,BT)

All trees are blazed, scribed, and
painted. Measurements are to nail in
side of tree, bearings are magnetic.

JEREMY PIPP

PROFESSIONAL

SURVEYOR

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971

Revised May 14, 1975

Revised Jan., 1983

Revised Oct., 1995

20032

20031