LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Menominee (County)	Located In:	Corner Code #			
1. Public Land Survey	TR TR TR				
2. Property Controlling in Section	S 28 T 36N R 25W S 28 T 36N R 25W S T R	2 16	16		
3. Miscellaneous Property in Sec.	S T R S T R		Register of Deeds Stamp & File Number		
4. Lot No. , Red 5. Private Claims	corded Plat	PAD	A B C D E F G H I J K L M		
I, Jeremy J. Pipp , in a field survey on 1/09/2012AD do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with 7 the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, 8 19 20 21 22 23 24 re-established, monumented, recovered, found as expressed below:					
NOTE: Not more than 2 corn on this certificate.	9 10 30 29 28 27 26 25 11 12 31 32 33 34 35 36				

- A. Description of original monument and accessories and/or subsequent restoration:
- (02) East One-Sixteenth corner common to Sections 21 and 28. Not set in original survey, no evidence of subsequent establishment.
- (16) East One-Sixteenth corner common to Sections 28 and 33. Not set in original survey, no evidence of subsequent establishment.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- (02) Corner position established mid-point and on-line between the North One-Quarter corner and the Northeast corner of Section 28.
- (16) Corner position established mid-point and on-line between the South One-Quarter corner and the Southeast corner of Section 28.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(02)	DNR monument	(16) DNR	monument
5" Spruce	N32E 19.33' (1/16S,BT)	17" White Pine	N48E 24.86' (1/16S,BT)
7" Spruce	S62E 13.48' (1/16S,BT)	8" White Pine	S40E 12.99' (1/16S,BT)
10" Cedar	\$22W 17.48' (1/16S,BT)	7" White Pine	\$70W 13.51' (1/16S,BT)
8" Maple			N26W 61.77' (1/16S,BT)
All trees are blazed, scribed, and		All trees are b	lazed, scribed, and
painted. Measurements are to nail in		painted Messu	rements are to nail in
side of tree, bearings are magnetic		sign for the sign of	ings are magnetic.

orgined by

Surveyor's Michigan License No.

V 30447

PIPP

July 16, 2012

TE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971.

For the Michigan Department of Natural Resource Office of Lange of Natural Resource Office Office

20012

EUNAZ WINENE

Revised May 14, 1975 Revised Jan., 1983 Rervised Oct., 1995