## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Menominee (County)	Located In:	Corner Code #				
1. Public Land Survey	T R T R					
2. Property Controlling in Section		25W POL E of 09				
3. Miscellaneous Property in Sec.	S T R		Register	of Deeds Stamp	s & File Number	
4. Lot No. , Rec 5. Private Claims	corded Plat		A B C	D E F G	H I J K	L M
above were in conformance with r	74, Michigan P.A. of 1970, the egulations and rules therefore	do hereby state ne corner points mentioned in lines 1 and as required in the current manual of surve	2 4 7 ey 5	-89	-1011-	12
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of 6 18 17 16 15 14  a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with 7 the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, 8 19 20 21 22 23 re-established, monumented, recovered, found as expressed below:						—13 —24
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.			9 10 30 11	29 28 6	-2726	-25-
	onument and accessories	and/or subsequent restoration:	12 31	-32   33	34 35	36-

(POL) Point on East-West One-Quarter Line of Section 28. Not set in original survey, no evidence of subsequent establishment.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(POL) Point on East-West One-Quarter Line of Section 28, lying 13 feet East of the Top of Bank of the Cedar River and 24 feet from Waters edge. Position falls along an E-W Fence line and is 12 feet East of a Pipe driven in at an angle to anchor the end of the fence

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

50447

(POL) 1" Pipe with Plastic Cap N34E 10.51' 6" Red Pine (POL,BT) 13" Red Pine S65W 15.23' (POI All trees are blazed, scribed, and (POL,BT) painted. Measurements are to nail in side of tree, bearings are magnetic.

JEREMY J. ROFESSIONA SURVEYOR

July 16, 2012

Signed by

Surveyor's Michigan License No.

ESSIO For the Michigan Department of Natural Resources, Office of Land and Facilities