

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

<u>Menominee</u> (County)	Located In:	Corner Code #
1. Public Land Survey	T 36N R 25W	D08
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S _____ T _____ R _____	_____
	S 20 T 36N R 25W	05
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____

4. Lot No. _____, Recorded Plat _____
 5. Private Claims _____

12/13/2012AD

I, Jeremy J. Pipp, in a field survey on 12/13/2012AD do hereby state

that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(D08) Center One-Quarter Corner of Section 20. Not set in original survey, no evidence of subsequent establishment.

(05) Center-North One-Sixteenth corner of Section 20. Not set in original survey, no evidence of subsequent establishment.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(D08) Corner position established at the intersection of the North-South and East-West One-Quarter lines of Section 20.

(05) Corner position established mid-point and on-line between the Center One-Quarter corner and the North One-Quarter corner of Section 20.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(D08)	DNR monument	(05)	DNR monument
9" Spruce	N11E 5.20' (1/4S,BT)	8" Tw. Maple	N32E 36.95' (1/16S,BT)
12" Cedar	S05E 19.81' (1/4S,BT)	8" Cedar	S88E 20.86' (1/16S,BT)
6" Cedar	S40W 22.79' (1/4S,BT)	5" Maple	S51W 13.12' (1/16S,BT)
5" Cedar	N73W 46.25' (1/4S,BT)	4" Maple	N62W 20.14' (1/16S,BT)

All trees are blazed, scribed, and painted. Measurements are to nail in side of tree, bearings are magnetic.

Signed by Jeremy J. Pipp Date July 18, 2013
 Surveyor's Michigan License No. 50447



For the Michigan Department of Natural Resources, Forest Resource Division

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													