

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Menominee (County)	Located In:	Corner Code #
1. Public Land Survey	T _____ R _____ T _____ R _____ T _____ R _____	_____
2. Property Controlling in Section	S 4 T 36N R 27W S 6 T 36N R 27W S _____ T _____ R _____	5 6 _____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____ S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat _____		
5. Private Claims		

Register of Deeds Stamp & File Number

1	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6			5		4		3		2		1	
3													
4	7			8		9		10		11		12	
5													
6	18			17		16		15		14		13	
8	19			20		21		22		23		24	
9													
10	30			29		28		27		26		25	
11													
12	31			32		33		34		35		36	
13													

I, Jeremy J. Pipp, in a field survey on 2/13/2012AD do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(05) Center-North One-Sixteenth corner of Section 4. Not set in original survey, Found
Capped Rebar (PS#26461) and Chest Blazed trees facing position.

(06) Northeast One-Sixteenth corner of Section 6. Not set in original survey, no evidence
of subsequent establishment.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(05) Calculated single proportionate Corner position on-line between the Center One-
Quarter corner and the North One-Quarter corner of Section 4. Found Capped Rebar checked
well for position was accepted. Set MDNR monument over the top of said existing monument.

(06) Corner position established at the intersection of the North and East One-Sixteenth
lines of Section 6.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(05) DNR monument
6" Ash N74E 40.25' (1/16S,BT)
16" Spruce S34E 28.19' (1/16S,BT)
6" Tamarack N82W 38.28' (1/16S,BT)
4" Ash N25W 15.38' (1/16S,BT)

All trees are blazed, scribed, and
painted. Measurements are to nail in
side of tree, bearings are magnetic.

Signed by Jeremy J. Pipp
Surveyor's Michigan License No. 50447

(06) DNR monument
6" Basswood N36E 16.82' (1/16S,BT)
6" Ash S28E 22.64' (1/16S,BT)
9" Ash S32W 4.55' (1/16S,BT)
5" Ironwood N30W 35.10' (1/16S,BT)

All trees are blazed, scribed, and
painted. Measurements are to nail in
side of tree, bearings are magnetic.

Date July 16, 2012
JEREMY J. PIPP
PROFESSIONAL SURVEYOR

For the Michigan Department of Natural Resources, Office of Land and Facilities

20019

20022

FOR THE STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971

Revised May 14, 1975

Revised Jan., 1983

Revised Oct., 1995