LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Menominee	_ Located In:	Corner Code #				
(County)						
1. Public Land Survey	T R T R					
2. Property Controlling in Section	S 4 T 36N R 27W S 4 T 36N R 27W S T R	RF64 E of 10 RF64 E of E3				
3. Miscellaneous Property in Sec.	S T R S T R		Register of De	eeds Stamp & Fil	e Number	
4. Lot No. , Red 5. Private Claims	corded Plat		A B C D	E F G H	I J K L N	
	2/13/201	12AD	2 5-5-		<u>-</u>	
	a field survey on 2/13/20		3 4 7 8 8 -	9-10-	11-12	
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey 5						
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of 6 18 17 16 15 14 13						
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with 7 the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, 8 19 20 21 22 23 re-established, monumented, recovered, found as expressed below:					23 24	
NOTE: Not more than 2 corn on this certificate.	9 10 30 29 11 12 31 32	33 34	26 25			
			13			

A. Description of original monument and accessories and/or subsequent restoration:

(C-W-SW 1/64) Center-West-Southwest One-Sixty-Fourth corner of Section 4. Not set in original survey, no evidence of subsequent establishment.

(W-W 1/64) West-West One-Sixty-Fourth corner of Section 4. Not set in original survey, no evidence of subsequent establishment.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(C-W-SW 1/64) Corner position established mid-point and on-line between the Southwest One-Sixteenth corner and the South One-Sixteenth corner on the West line of Section 4.

(W-W 1/64) Corner position established mid-point and on-line between the West One-Sixteenth corner on the South line and the Southwest corner of Section 4.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(C-W-SW 1/64)	DNR monument	(W-W 1/64) PK Nail with MDNR Ref. Washer
3" Maple	N23E 24.62' (1/64S,BT)	8" Ash N58E 64.82' (1/64S,BT)
3" Maple	S73E 9.31' (1/64S,BT)	Powerpole #MAP9-61E S49E 58.11'
4" Maple	S73W 7.51' (1/64S,BT)	5" Ash S22W 58.44' (1/64S,BT)
•	N38W 51.91' (1/64S,BT)	12" Red Pine NO8W 66.79' (1/64S,BT)
All trees are blazed, scribed, and		All treasure blazed, scribed, and
painted. Measurements are to nail in		painted as ments are to nail in side
side of tree, b	earings are magnetic.	Totree, bearing are magnetic.
Signed by	- keing (4)	JEREMY Date July 16, 2012

Surveyor's Michigan License No.

50447

PROFES

For the Michigan Department of Natural Resource

ffice of Lan

Rervised Oct., 1995