

# SURVEY & REMONUMENTATION

FEB 11 1998

Approved by Menominee County  
Land Survey Remonumentation  
Peer Group Under Act 345 Of

P.A. Of 1990 On 12/30/97 2

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

### SECTION

For corners in

MENOMINEE

(County)

Located in:

Corner Code #

1. Public Land Survey

36N R 27W

J-07

T R

T R

T R

2. Property Controlling  
in Section

S

T R

S

T R

3. Miscellaneous  
Property in Sec.

S

T R

S

T R

4. Lot No. , Recorded Plat

5. Private Claims

I, William Lenca, in a field survey on Dec. 01, 1997 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

REGISTERED FOR RECORD  
97 DEC 30 PM 4:06  
PAGE 618, BKS  
REGISTER OF DEEDS  
MENOMINEE COUNTY

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	10		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

- 1852: Original Survey by Francis Coleman - B.T.'s - Fir, 10" - N40°E - 38 lks.; Sugar, 18" - S73°W - 09 lks. All original evidence for this corner has been destroyed by logging and farming activities.
- 1963: L.C.R.C. 797, Vol. 2, by M.S.H.D. Survey Chief C.C. Lindgren states, "Found: Fe. corner, a Fe. post as 1/4 corner as described in original notes." TIES: Maple, 6" - N75°E - 18.09'; Maple, 4" - N20°W - 18.54'; Birch, 4" - N45°W - 11.05'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

We recovered a 1" diameter Iron Pipe at an ancient fence corner and 2 B.T.'s as L.C.R.C. 797, Volume 2 (6" Maple - N75°E - 18.09' - now a 12" dia. Maple; 4" Maple - N20°W - 18.54' - now 8" dia. Maple). Fences run North - East, and West. This position has been accepted and used by local surveyors for many years, fits existing lines of occupation, and is accepted as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 2" dia. Aluminum Pipe/3-1/4" dia. Alum cap stamped for corner location:

12" dia. Maple (Old B.T.)	N75°E	17.94 feet	Scr. NBT
8" dia. Ironwood	S84°W	22.51 feet	Scr. NBT
8" dia. Maple (Old B.T.)	N20°W	18.85 feet	Scr. NBT
Metal Survey Sign Post	South	0.8 feet	



NOTE: All bearings are magnetic bearings. All distances are measured with steel tape. Distances to trees are to nail in side of tree.

Signed by William Lenca  
Surveyor's Michigan License No. 26461

Date Dec. 03, 1997