

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Menominee (County)	Located In:	Corner Code #
1. Public Land Survey	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S 21 T 36N R 28W	07
	S 21 T 36N R 28W	09
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat _____		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

, Jeremy J. Pipp, in a field survey on 3/26/2013AD do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(07) North One-Sixteenth corner common to Sections 21 and 22. Not set in original
survey, no evidence of subsequent establishment.

(09) Center-East One-Sixteenth corner of Section 21. Not set in original survey, no
evidence of subsequent establishment.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(07) Corner position established mid-point and on-line between the East One-Quarter
corner and the Northeast corner of Section 21.

(09) Corner position established mid-point and on-line between the Center One-Quarter
corner and the East One-Quarter corner of Section 21.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(07)	DNR monument	(09)	DNR monument
9" Cedar	N05W 12.75' (1/16S,BT)	6" Tri. Maple	N55E 34.86' (1/16S,BT)
14" Cedar	S24E 23.76' (1/16S,BT)	10" Maple	S48E 9.86' (1/16S,BT)
6" W. Birch	S41W 30.19' (1/16S,BT)	6" Maple	S62W 20.64' (1/16S,BT)
6" Cedar	N56W 14.25' (1/16S,BT)	6" Maple	N62W 16.96' (1/16S,BT)

All trees are blazed, scribed, and
painted. Measurements are to nail in
side of tree, bearings are magnetic.

Signed by Jeremy J. Pipp Date August 08, 2013
Surveyor's Michigan License No. 50447

For the Michigan Department of Natural Resources, Forest Resource Division

20204

20205

