

**LAND CORNER RECORDATION CERTIFICATE**  
**Filing Requirement of Act 74, Mich. P.A. 1970 as Amended**

For corners in

<u>Menominee</u> (County)	Located In:	Corner Code #
1. Public Land Survey	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S 32 T 36N R 28W	10
	S 32 T 36N R 28W	11
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, Jeremy J. Pipp, in a field survey on 3/25/2013AD do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(10) South One-Sixteenth corner common to Sections 31 and 32. 1996: William Lenca (PS#26461) noted set monument.

(11) Southwest One-Sixteenth corner of Section 32. Not set in original survey. 1986: William Lenca (PS#26461) noted set monument.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(10) Corner position established mid-point and on-line between the West One-Quarter corner and the Southwest corner of Section 32. Accepted found PS#26461 Capped rebar as marking the corner position.

(11) Corner position established at the intersection of the South and West One-Sixteenth lines of Section 32. Accepted found PS#26461 Capped rebar as marking the corner position.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(10)	DNR monument	(11)	DNR monument
9" Cedar	N16E 4.20' (1/16S,NBT)	11" Maple	S11W 27.89' (1/16S,NBT)
6" Cedar	S28E 21.03' (1/16S,NBT)	10" Cedar	S81W 65.40' (1/16S,NBT)
6" Cedar	S21W 21.70' (1/16S,NBT)	8" Cedar	N44W 35.26' (1/16S,NBT)
9" B. Spruce	N64W 6.28' (1/16S,NBT)	6" B. Spruce	N22W 44.69' (1/16S,NBT)

All trees are blazed, scribed, and painted. Measurements are to nail in side of tree, bearings are magnetic.

Signed by Jeremy J. Pipp Date July 30, 2013  
 Surveyor's Michigan License No. 50447



For the Michigan Department of Natural Resources, Forest Resource Division

20201  
20200

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971  
 Revised May 14, 1975  
 Revised Jan., 1983  
 Revised Oct., 1995