LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Menominee (County)	_ Located In:	Corner Code #						
1. Public Land Survey	TR TR							
2. Property Controlling in Section	S 21 T 36N R 28W S 21 T 36N R 28W S T R							
3. Miscellaneous Property in Sec.	S T R S T R		Regi	ster of De	eds Stamo	& File	. Numt	oer
4. Lot No. , Red 5. Private Claims	corded Plat		1 A B	C D E	F G	H I	JΚ	LM
	3/26/20	013AD	2 6-	╁╌┋╌┼	╌┋╌┼╼	}-	-2	— <u></u>
, Jeremy J. Pipp , i	n a field survey on 3/26/20	013AD do hereby state	3	 - - 	- 	+-		
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2						-12-		
above were in conformance with regulations and rules therefore as required in the current manual of survey 5								
nstructions of the United States Department of the Interior, Bureau of Land Management or by a decree of 6 18 17 16 15 14 13								
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with 7 the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, B 19 20 21 22 23 26								
re-established, monumented, recov		20-	21	22-	-23	24		
	9	1 1 1	191	1				
NOTE: Not more than 2 corr	1030-	 29- 	<u> </u>	27	-26-	 25		
on this certificate.	11	 		++	\dashv			
			12 -31-	32	33	³ 1	-35 	36
A Description of original monument and accessories and/or subsequent restoration								

- Description of original monument and accessories and/or subsequent restoration:
- (14) South One-Sixteenth corner common to Sections 21 and 22. Not set in original survey, no evidence of subsequent establishment.
- (16) East One-Sixteenth corner common to Sections 21 and 28. Not set in original survey; 1927: J. Lymer set Iron Bar (map found in records of William Lenca PS#26461).
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- (14) Corner position established mid-point and on-line between the East One-Quarter corner and the Southeast corner of Section 21.
- (16) Accepted found 3/4" Iron Bar & Set MDNR monument over the top of existing monument.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(14)	DNR monument	(16) DNR monument
9" ASH	N56E 16.52' (1/16S,BT)	9" W. Pine N38E 33.90'(1/16S,NBT)
11" ASH	S67E 20.53' (1/16S,BT)	EX 22" W. Pine N78E 5.15' (- , -)
8" Spruce	S03E 11.05' (1/16S,BT)	9" W. Pine S37W 50.67'(1/16S,NBT)
3" ELM	N22W 22.71' (1/16S,BT)	22" W. Pine N77W 36.50'(1/16S,NBT)
All trees a	are blazed, scribed, and	All the blazed, scribed, and
	Measurements are to nail in	parter Mices rements are to nail in
side of tre	ee, bearings are magnetic.	of tree, bearings are magnetic.

Signed by

For the Michigan Department of Matural Resou

PROFESSIONAL

August 08, 2013

Surveyor's Michigan License No.

N STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971