

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Menominee Located In: Corner Code #
1. Public Land Survey T 36N R 28W F04
2. Property Controlling in Section S 9 T 36N R 28W 09
3. Miscellaneous Property in Sec. S T R
4. Lot No. , Recorded Plat
5. Private Claims

Register of Deeds Stamp & File Number

Table with 13 rows and 13 columns (A-M). Contains numerical data for registration stamp.

I, Jeremy J. Pipp, in a field survey on 3/27/2013AD do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(F04) Center One-Quarter Corner of Section 9. Not set in original survey. Found PS#51484 capped 5/8" rebar (N59° 07' 22"W, 3.69' from calculated true position).

(09) Center-East One-Sixteenth corner of Section 9. Not set in original survey, no evidence of subsequent establishment.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(F04) Corner position established at the intersection of the North-South and East-West One-Quarter lines of Section 9. Found capped rebar not accepted.

(09) Corner position established mid-point and on-line between the Center One-Quarter corner and the East One-Quarter corner of Section 9.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(F04) DNR monument: 13" Maple N57E 32.00' (1/4S,NBT), 17" R. Pine S36W 84.65' (1/4S,NBT), 17" Maple S79W 63.51' (1/4S,NBT), 25" W. Pine N27W 107.16' (1/4S,NBT). All trees are blazed, scribed, and painted. Measurements are to nail in side of tree, bearings are magnetic.
(09) DNR monument: 7" Tamarack N61E 18.56' (1/16S,BT), 12" Cedar S80E 19.78' (1/16S,BT), 4" ASH S36W 24.69' (1/16S,BT), 13" Tamarack N24W 3.47' (1/16S,BT). All trees are blazed, scribed, and painted. Measurements are to nail in side of tree, bearings are magnetic.

Signed by [Signature] Date August 08, 2013
Surveyor's Michigan License No. 50447

For the Michigan Department of Natural Resources Forest Resource Division

