

APR 06 1999

P.A. 01-1990 On 12/14/98  
Chairman

SECTION

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

MENOMINEE

(County)

Located In:

Corner Code #

1. Public Land Survey

T36N R 28W

E-13

T R

T R

T R

2. Property Controlling  
in Section

S T R

S T R

3. Miscellaneous  
Property in Sec.

S T R

S T R

4. Lot No. , Recorded Plat

5. Private Claims

(SAME AS CORNER E-01, T35N - R28W.)

I, William Lenca, in a field survey on July 08, 1998 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- 1848: Original Survey by H. Brevoort, Jr. - B.T.'s - W. Oak, 8" - N71°E - 15 lks.; Dry Hemlock, 9" - N07°W - 14 lks. All original evidence for this corner has been destroyed by logging activities.
- 1959: L.C.R.C. No. 42 (Vol. 2) by Billy D. Buckler, corner was re-established by Dbl Prop. measure from corners 1 mile west, 1 mile north, 1/2 mile South and Fc. Cor. 1 mile East. Corner falls in open clearing - No original evidence - Set 1" Pipe/4" Brass cap: 24" W. Pine - S11°E, 189.5 lks; 36" W. Pine - N26°E - 225 lks.
- 1992: L.C.R.C. No. 736 (Bk 3) by Paul Bressette - SEE BACK

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

We found a 1" Pipe with a 4" Brass Cap and 2 B.T.'s in a location as indicated in Land Corner Recordation Certificate Number 42. We also recovered 4 B.T.'s as described in L.C.R.C. No. 736 (Book 3). The corner was re-established by double proportion according to L.C.R.C. No. 42 (Vol. 2), and is therefore accepted as a careful and faithful reestablishment of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Accepted existing 1" Iron Pipe with 4" Brass Cap for corner location:

|                        |       |             |          |
|------------------------|-------|-------------|----------|
| 12" dia. Maple         | N70°E | 94.70 feet  | Scr. NBT |
| 36" dia. White Pine    | S06°E | 125.99 feet | Scr. NBT |
| 12" dia. Cherry        | S43°W | 57.46 feet  | Scr. NBT |
| 6" dia. Cherry         | N07°W | 64.63 feet  | Scr. NBT |
| Metal Survey Sign Post | North | 1.0 feet    |          |

NOTE: All bearings are magnetic bearings. All distances are measured with steel tape. Distances to trees are to nail in side of tree.

Signed by William Lenca

Date Dec. 11, 1998

Surveyor's Michigan License No. 26461

RECEIVED FOR RECORD  
30 DEC 14 PM 3:23  
FILE # 693 BKS  
SARAH A. MORRISON  
REGISTER OF DEEDS  
MENOMINEE, MI 49858

Register of Deeds Stamp & File Number

| A  | B  | C | D  | E | F  | G | H  | I | J  | K | L  | M |
|----|----|---|----|---|----|---|----|---|----|---|----|---|
| 1  |    |   |    |   |    |   |    |   |    |   |    |   |
| 2  | 6  |   | 5  |   | 4  |   | 3  |   | 2  |   | 1  |   |
| 3  |    |   |    |   |    |   |    |   |    |   |    |   |
| 4  | 7  |   | 8  |   | 9  |   | 10 |   | 11 |   | 12 |   |
| 5  |    |   |    |   |    |   |    |   |    |   |    |   |
| 6  | 18 |   | 17 |   | 16 |   | 15 |   | 14 |   | 13 |   |
| 7  |    |   |    |   |    |   |    |   |    |   |    |   |
| 8  | 19 |   | 20 |   | 21 |   | 22 |   | 23 |   | 24 |   |
| 9  |    |   |    |   |    |   |    |   |    |   |    |   |
| 10 | 30 |   | 29 |   | 28 |   | 27 |   | 26 |   | 25 |   |
| 11 |    |   |    |   |    |   |    |   |    |   |    |   |
| 12 | 31 |   | 32 |   | 33 |   | 34 |   | 35 |   | 36 |   |
| 13 |    |   |    |   |    |   |    |   |    |   |    |   |

