

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Menominee (County) Located In: Corner Code #
1. Public Land Survey T 37N R 25W L07
T 37N R 25W L06
2. Property Controlling Section S T R
S T R
S T R
3. Miscellaneous Property in Sec. S T R
S T R

4. Lot No. , Recorded Plat
5. Private Claims

2/24/2014
Jeremy J. Pipp, in a field survey on 2/24/2014 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(L07) Quarter corner common to Sections 13 and 24. 1853: George Adair, DS. Set quarter section
post witnessed by Tamarack 9 N53E 35 links (23.10'), Cedar 11 S74 1/2W 16 links (10.56'). 1968:
Michigan DNR (Frank Bray PS#13575) Set 1" pipe with 4" Aluminum cap from found wood posts and
Tamarack OBT, witnessed by 7" Cedar N69W 21 links (13.86'), 9" Cedar N73E 33 links (21.78').

(L06) Center One-Quarter Corner of Section 13. Not set in original survey, no evidence of
subsequent establishment.

3. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(L07) Accepted found MDNR Monument and Four NBT's (all living; two MDNR, two by unknown persons) as
a careful and faithful PERPETUATION of the position of the original corner.

(L06) Corner position established at the intersection of the North-South and East-West One-Quarter
lines of Section 13.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(L07) DNR monument
EX 10" Cedar N78E 22.44' (1/4S,NBT)
EX 7" Cedar S41E 9.88' (1/4S,NBT)
EX 9" Cedar S26W 27.94' (1/4S,NBT)
EX 8" Cedar N64W 14.21' (1/4S,NBT)

All trees are blazed, scribed, painted,
and signed. Measurements are to nail in
side of tree, bearings are magnetic. A
Metal rail was set South 1.5 feet.

Signed by [Signature]
Surveyor's Michigan License No. 50447

For the Michigan Department of Natural Resources

(L06) DNR monument
10" Cedar N41E 14.99' (1/4S,BT)
5" Cedar S60E 10.84' (1/4S,BT)
10" Cedar S37W 16.80' (1/4S,BT)
5" Cedar N82W 3.69' (1/4S,BT)

All trees are blazed, scribed, and
painted. Measurements are to nail in
side of tree, bearings are magnetic.

Signed by [Signature] July 9, 2014



Table with 13 rows and 13 columns (A-M) for Register of Deeds Stamp & File Number. Contains numbers 1-36 in a grid pattern.