

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF:-	LOCATED IN:-	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 37 N. S., R. 27 E. W.	D-11, E-10, F-9
2. PROPERTY CONTROLLING IN SECTION	29, T. 37 N. S., R. 27 E. W.	7
3. MISCELLANEOUS PROPERTY IN SECTION	, T. N. S., R. E. W.	
4. LOT NO.	, RECORDED PLAT	
5. PRIVATE CLAIMS		

REGISTER OF DEEDS STAMP AND
FILING NUMBER

I, David B. Babbitt, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on 12/13, 1982, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:
D-11-S 1/4 Cor. Sec. 29; wood post - Hemlock 12"-N35E-40 lks; Sugar 10"-S20W-34 lks.
E-10-East 1/4 corner Section 29; wood post - Cedar 5"-N27E-23 lks., Spruce 6"-S46W-25 lks.
F-9- North 1/4 corner of Sec. 28; wood post-Fir 10"-N10E-6 lks, Cedar 6"-S45W-4 lks.
7 - N 1/16 Cor. on East Boundary Sec, 29, not previously established.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:
D-11 Set M.P.O.L. between the S.W. and S.E. Sec. Cors. of Sec. 29. No signs of O.B.T.s.
E-10 Set M.P.O.L. between the N.E. and S.E. Sec. Cor.s of Sec. 29. Many Cedar Stps. in the area but none could be identified as O.B.T.s.
F-9 Set in center line of E-W blacktop road and in line with very old fence and field boundary North. Measurements East to N.E. Cor. of Sec. 28 and West to the N 1/4 Cor. of Sec. 29 are reasonable and swamp calls both East and West also check well. Cor. falls in a recent road cut.
7 - Set M.P.O.L. Betw. the East 1/4 Cor. and the N.E. Sec. Cor. of Sec. 30.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
D-11 1" pipe, 4" aluminum cap; 10" Cedar N73°W 41.2'; 8" Cedar N21°W 44.2'; 5" Balsamfir N59°E 2.0'; 5" Twin R. Maple S14°W 20.0'.
E-10 1" pipe, 4" aluminum cap; 5" Cedar N76°W 4.6'; 6" Cedar N60°E 4.2'; 5" Cedar S58°E 5.5'; 4" Cedar S40°W 1.7'.
F-9 Menominee County Survey Monument set flush with blacktop surface; Sugar Maple (Twin) 7" N8°W 120.3'; Spruce 4" N46°W 167.0'; Cedar 10" N74°W 224.2'; Pass With Care Sign S74°E 57.5'
7 - 1" pipe, 4" aluminum cap; 4" B. Spruce N3°W 14.1'; 2" B. Spruce N52°E 18.0'; 3" B. Spruce S7°E 11.6'; 2" B. Spruce S60°W 7.2'.

SIGNED BY David B. Babbitt DATE 12-16-82

SURVEYOR'S MICHIGAN REGISTRATION NO. 21558 (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____

CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____

MICHIGAN REGISTERED LAND SURVEYOR

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET