

SURVEY & REMONUMENTATION

APR 24 1995

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
MENOMINEE
(County)

Located In:

Corner Code #

- | | | |
|------------------------------------|-------------|------|
| 1. Public Land Survey | T 38N R 26W | M-09 |
| | T R | |
| | T R | |
| | T R | |
| 2. Property Controlling in Section | S T R | |
| | S T R | |
| 3. Miscellaneous Property in Sec. | S T R | |
| | S T R | |

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

William Lenca

Jul 27

94

I, _____, in a field survey on _____, 19 _____, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- 1848: Original Survey (Township Exterior) by James H. Mullet - B.T.'s - Sugar, 10" - N39°W - 34 lks; Beech, 4" - S53°W - 32 lks - All original evidence for this corner has been destroyed by farming activities.
- 1899: Albert Haas, County Surveyor, made a survey of Section 25, T38N-R26W and describes this corner as "Set Cedar stake from Government B.T."

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

In a 1987 survey of Section 24, T38N-R26W we set a 5/8" x 24" Iron rod/Ident. cap in the centerline of an old lane running West and in line with an old fence line running South. In our 1994 remonumentation of this corner, we found the 5/8" x 24" Iron Rod with a plastic identification cap set in location as described. The measurement to the 1/4 corner 1/2 mile West is 2672.51 feet compared with Haas' distance of 2666.4 feet. We accepted the existing corner as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 2-1/2" dia. alum. Pipe 30" long/3-1/4" dia. Alum. cap stamped for corner location:

Twin 9" dia. Maples	N57°E	21.77 feet	Scr. NBT
10" dia. Maple	S35°W	41.10 feet	Scr. NBT
8" dia. Maple	S65°W	30.12 feet	Scr. NBT
9" dia. White Ash	N38°W	12.66 feet	Scr. NBT
Survey Sign Post	S52°W	1.7 feet	

NOTE: All bearings are magnetic bearings. All distances are measured with steel tape. Distances to trees are to nail in side of tree.

Signed by William Lenca

Date

Dec. 14, 1994

Surveyor's Michigan License No. 26461

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983

Approved by Menominee County
Land Survey Remonumentation
Peer Group Under Act 345 of

P.A. of 1999 On DEC 16 1994
Alvin Davis RLS 16926
REGISTER OF DEEDS
MENOMINEE

RECEIVED FOR RECORD
4 DEC 27 AM 10:45
PAGE # 156 BK 4
BARBARA MORRISON
REGISTER OF DEEDS
MENOMINEE 498358

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

