STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

LAND CORNER RECORD

		Menominee	COUNTY
		т 140 и	R _25 W
DESCRIPTION OF CORNER	Section corner for Sections	<u>29/28</u> 32/33	
CORNER MONUMENT	1" iron pipe with 4" aluminu	ш сар	
DATE MONUMENT PLACED AND W	ITNESSED 4/29/71 F. J. Bra	y	
WITNESSES TO CORNER	7" Hemlock (S. 33) (NBT) S 7	5°E, 4.81	
N •33	9" Hemlock (S. 32) (NBT) S 2	20°W, 11.9'	
	AND		

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from wood post. Old, down, blazed cedar facing the corner. Signature tree with Slater's and other names that had been blazed over thirty years ago. Old line running north from this location.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED REGISTERED LAND SURVEYOR

DATE $\frac{6/8}{7}$

Frank J. Bray

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing

R 4047 Rev. 10/68