## STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

## LAND CORNER RECORD

	_	40 и	R	2년 교
	19			
DESCRIPTION OF CORNER Section corner for Sections		/20 /29		
CORNER MONUMENT 1½" x 30" iron pipe (buried	<u>.</u>			
DATE MONUMENT PLACED AND WITNESSED 4/29/71				
WITNESSES TO CORNER 7" Aspen (NBT) S 06°W, 34.	31			
1h" Cedar (NBT) N 56°W, 78.	91			
AND				<u> </u>

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was placed in line with old fence lines to the east and to the south and with a gravel road to the north. Land features check well with original notes.

No original evidence was found.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGN

GNED Franklofin

DATE \_\_\_\_6

Frank J. Bray

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing

R 4047 Rev. 10/68