

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Menominee (County) Located In: Corner Code #
1. Public Land Survey T 40N R 25W E09
T 40N R 25W D11
2. Property Controlling Section S T R
S T R
S T R
3. Miscellaneous Property in Sec. S T R
S T R

4. Lot No. , Recorded Plat
5. Private Claims

Jeremy J. Pipp, in a field survey on 6/03/2014 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

1. Description of original monument and accessories and/or subsequent restoration:

(E09) Section corner common to Sections 20, 21, 28, and 29. 1852: Harvey Mellen, DS. Set section
corner post witnessed by Tamarack 12 S50W 45 links (29.70'), Tamarack 10 N32E 26 links (17.16').
1964: Kimberly Clark Corp. (Neal Sperhake PS#7876) Set 1" pipe with 4" Aluminum cap on site of
original post as determined from existing original bearing tree (Tamarack 12 S50W 45 lks) witnessed
by 9" Tamarack S04W 40 1/2 links (26.73'), 6" Tamarack N18E 42 1/2 (28.05'), 10" Cedar S50E 69 1/2
(45.87'), 5" Cedar N23W 20 1/2 (13.53').

(D11) Quarter corner common to Sections 29 and 32. 1852: Harvey Mellen, DS. Set Quarter section
corner post witnessed by Tamarack 6 S45E 22 links (14.52'), Tamarack 9 S70W 4 links (2.64'). 1971:
Michigan DNR (Frank Bray PS#13575) Set 1" pipe with 4" Aluminum cap Midway and online between
section corners east & west witnessed by 6" Cedar N03W 24.3', 5" Cedar S84W 5.5'.

3. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(E09) Accepted found Kimberly Clark monument and Four NBT witnesses (all living). Position is
accepted as a careful and faithful PERPETUATION of the position of the original corner.

(D11) Accepted found MDNR Monument and Two NBT Witnesses (both living). Position is accepted as a
careful and faithful REESTABLISHMENT of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(E09) Kimberly Clark monument (D11) DNR monument
EX 10" Tamarack N21E 27.89' (S 21,NBT) 10" Cedar N58E 45.38' (1/4S,NBT)
EX 12" Cedar S38E 45.40' (S 28,NBT) 9" Cedar S22W 27.32' (1/4S,NBT)
EX 12" Tamarack S14W 26.25' (S 29,NBT) EX 15" Cedar West 5.29' (1/4S,NBT)
EX 8" Cedar N17W 13.76' (S 20,NBT) EX 10" Cedar North 24.33' (1/4S,NBT)
All trees are blazed, scribed, painted, and signed. Measurements are to nail in
side of tree, bearings are magnetic. A Metal sign post was set South 1.5 feet.
Signed by [Signature] Date July 9, 2014

Surveyor's Michigan License No. 50447

For the Michigan Department of Natural Resources

20344

20345



Register of Deeds Stamp & File Number

Table with 13 rows and 13 columns (A-M) containing numbers 1-36 and survey points marked with dots.