

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

or corners in

Menominee (County) Located In: Corner Code #
Public Land Survey
Property Controlling Section
Miscellaneous Property in Sec.

Lot No. Recorded Plat
Private Claims

Jeremy J. Pipp, in a field survey on 8/18/2014 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
in this certificate.

1. Description of original monument and accessories and/or subsequent restoration:

(05) Center-North One-Sixteenth corner of Section 10. Not set in original survey, no evidence of
subsequent establishment.

(07) North One-Sixteenth corner common to Sections 1 [T41N-R26W] and 6 [T41N-R25W]. Not set in
original survey, no evidence of subsequent establishment.

2. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(05) Corner position established mid-point and on-line between the Center One-Quarter corner and
the North One-Quarter corner of Section 10.

(07) Corner position established proportionately and on-line between the East One-Quarter corner
and the Northeast corner of Section 1.

3. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(05) DNR monument
15" Cedar N32E 22.11' (1/16S,BT)
11" Cedar S38E 43.12' (1/16S,BT)
10" Cedar S83W 13.05' (1/16S,BT)
17" Cedar N42W 44.60' (1/16S,BT)

All trees are blazed, scribed, and
painted. Measurements are to nail in
side of tree, bearings are magnetic.

Signed by
Surveyor's Michigan License No. 50447

For the Michigan Department of Natural Resources

(07) DNR monument
8" Tamarack N42E 11.82' (1/16S,BT)
10" Tamarack S71E 3.78' (1/16S,BT)
7" B. Spruce S42W 4.74' (1/16S,BT)
12" Tamarack N32W 9.14' (1/16S,BT)

All trees are blazed, scribed, and
painted. Measurements are to nail in
side of tree, bearings are magnetic.

Date August 25, 2014



Table with 13 rows and 13 columns (A-M) for Register of Deeds Stamp & File Number.