

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Menominee (County) Located In: Corner Code #
1. Public Land Survey
2. Property Controlling Section
3. Miscellaneous Property in Sec.
4. Lot No. , Recorded Plat
5. Private Claims

3/20/2014
Jeremy J. Pipp, in a field survey on 3/20/2014 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(02) East One-Sixteenth corner common to Sections 9 and 16. Not set in original survey, no evidence of subsequent establishment.

(09) Center-East One-Sixteenth corner of Section 16. Not set in original survey, no evidence of subsequent establishment.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(02) Corner position established mid-point and on-line between the North One-Quarter corner and the Northeast corner of Section 16.

(09) Corner position established mid-point and on-line between the Center One-Quarter corner and the East One-Quarter corner of Section 16.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(02) DNR monument
5" Spruce N02W 29.57' (1/16S,BT)
11" Tamarack S71E 15.66' (1/16S,BT)
8" Spruce S02W 14.09' (1/16S,BT)
4" Spruce S64W 6.83' (1/16S,BT)
All trees are blazed, scribed, and painted. Measurements are to nail in side of tree, bearings are magnetic.
(09) DNR monument
8" Tamarack N35E 71.50' (1/16S,BT)
4" Spruce S39E 63.93' (1/16S,BT)
5" Tamarack S47W 41.99' (1/16S,BT)
9" Tamarack N59W 26.10' (1/16S,BT)
All trees are blazed, scribed, and painted. Measurements are to nail in side of tree, bearings are magnetic.

Signed by [Signature] Date July 9, 2014
Surveyor's Michigan License No. 50447

Table with 13 rows and 13 columns (A-M). Contains numbers 1-36 and a grid of dots representing survey points.