LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

| • | | • |
|----|---------|-------|
| 05 | corners | " " " |
| | | |

| Menominee (County) | _ Located In: | Corner Code # | | |
|--|--|---|--------------------|--|
| I. Public Land Survey | TR TR | | | |
| 2. Property Controlling n Section | S 16 T 41N R 261 S T R S T R | W 05 | 467 | |
| 3. Miscellaneous Property in Sec. | S T R S T R | | Register of Deeds | s Stamp & File Number |
| 1. Lot No, Red 5. Private Claims | corded Plat | | A B C D E | F G H I J K L M |
| , Jeremy J. Pipp , in | n a field survey on 9/1 | 7/2014 do hereby state | 3 | |
| above were in conformance with instructions of the United States | regulations and rules therefore as Department of the Interior, Bureau | required in the current manual of surve of Land Management or by a decree of 4 and 5 above were in conformance with | ey 5 of 6 18 17 | - 10 - 11 - 12 - 16 - 15 - 14 - 13 - 1 |
| | d of Land Surveyors or by a D | ecree of a Court of Law; established | | 21 22 23 24 |
| NOTE: Not more than 2 corners, all in the same town and range, may be recorded | | | 10 30 29 | -28 -27 -26 -25 |
| on this certificate. | | | 12 31 32 | 33 34 35 36 |

(05) Center-North One-Sixteenth corner of Section 16. Not set in original survey. Found 3/4" PVC pipe 3 feet high located 7 feet South of Calculated location.

3. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

4. Description of original monument and accessories and/or subsequent restoration:

(05) Corner position established mid-point and on-line between the Center One-Quarter corner and the North One-Quarter corner of Section 16. Found PVC pipe not accepted.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(05) DNR monument

10" Spruce N53E 29.15' (1/16S,BT)

7" Spruce S34E 38.63' (1/16S,BT)

8" Spruce S25W 37.78' (1/16S,BT)

6" Tw. Ironwood N01W 23.48' (1/16S,BT)

All trees are blazed, scribed, and painted. Measurements are to nail in side of tree, bearings are magnetic.

aremy 50447

JEREMY J.
PIPP
PROFESSIONAL
SURVEYOR
NO.
50447
Date S

September 17, 2014

Surveyor's Michigan License No.

For the Michigan Department of Natural Resources, Forest Resources Division

Rervised Oct., 1995

Signed by