

FEB 06 1998

Montmorency County Remonumentation

SECTION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

Liber 00012 Page 0286

For corners in

MONTMORENCY
(County)

Located In:

Corner Code ~~##~~

1. Public Land Survey

29N 1E

G - 9

T R

T R

T R

T R

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous
Property in Sec.

S T R

S T R

STATE OF MICHIGAN
MONTMORENCY COUNTY
Recorded & Filed

12-16-1997 10:52:03

A. PANGAN-MCELROY
REGISTER OF DEEDS
Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat

5. Private Claims

I, DONALD E MARLATT, in a field survey on 6/17, 19 97,
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the
current manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a
Court of Law; established, re-established, monumented, re-monumented, recovered, found as
expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

A. Description of original monument and accessories and/or subsequent restoration:

G - 9 CORNER COMMON TO SEC.'S 21-22-27 & 28.

GLO COR. SET BY LEWIS CLASON APRIL 1840. Y.PINE 12"-N50°W-13 L., Y.PINE 7"-S41°E-18 L.

F. SMITH NOTES. STEVENS 8/3/34. 1/2"X 30"BAR. FE.POST 12" S52°W 45', W.OAK 10" S42°E 86.4'.

TWIN LAKES SUB. BY F. SMITH 6/12/45. L. 1, OF PLATS, P. 62.

GREEN SPRUCE ACRES BY J.L.SCOTT 10/3/60. L. 2, OF PLATS, P. 30.

SURVEY BY R.S.SCOTT ASSO. INC. 8/1/90. L. 3, P. 557. FOUND 1/2"BAR IN MON. BOX.

N45°W 46.62' CONC. MONUMENT, N45°E 70.94' 1/2" & RLS CAP, S45°E 70.39' 1/2"BAR.

(OUT OF PLACE)

MONTMORENCY COUNTY ROAD PLANS DATED 6/26/78. S60°30'W 82.48' T. POLE, S13°45'W 41.7' BLACK
OAK. S42°E 86.0' 10"W.OAK.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

G - 9 CORNER COMMON TO SEC.'S 21-22-27 & 28.

FOUND 1/2" AND CAP#18660 IN MON. BOX.

APPROVED BY
PEER GROUP

JUN 20 97

L.B.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G - 9 CORNER COMMON TO SEC.'S 21-22-27 & 28.

PLACE REMON. CAP ON 1/2"ROD IN MON. BOX.

S47°W 10"J.PINE 93.05'

N35°W P.POLE 53.3'

N40°E T. POLE 57.9'

S49°E T.POLE 54.49'

WITNESSES ARE MARKED WITH 40 PENNY SPIKES AND P.S. TAGS #18660.

APPROVED BY PEER GROUP JUNE 20, 1997 as THE BEST AVAILABLE EVIDENCE OF THE POSITION
OF THE ORIGINAL CORNER.

Signed by Donald E Marlatt

Date 12/15/1997

Surveyor's Michigan License No. 18660

