## STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

## L'AND CORNER RECORD

			MO	HCY COUNTY		MTY	
		т		<u> </u>	R	2	E
DESCRIPTION OF CORNER	Sec. corner common	to Sections S	1 & 3	2			
CORNER MONUMENT	Set Dept. Monument						
DATE MONUMENT PLACED A	AND WITNESSED 12	-14-70					
WITNESSES TO CORNER							
N	7" Oak	N 30	W	<del></del>		20.	<u>7'</u>
31	12" J. Pine AND	N 41	E			19.5	7'
CIRCLE CORNER REGIS	TERED			_ <u></u>			

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found during retracement survey of T28N-R2E. Found old wood post bottom, as established in a previous survey by persons unknown, and noted in CCC survey. Best available evidence. Corner to Sections 5-6, T28N-R2E is 23.1' West.

SURVEYOR'S SEAL

SIGNED

REGISTERED LAND SURVEYOR 10068

DISTRIBUTION:

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing

R 4047 Rev. 10/68