## LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

Received MONTHORENCY COUNTY, MI 01-24-2012 09:37 am.

For Corners In: Montmorency (County)		Located	i In	Corner Code #
(Oddin))				
1. Public Land Survey		T 29N	R 03E	B-8
2. Property Controlling		·	- ``——	
in Section	S	T	R	
	s	т — —	R	
Miscellaneous     Property in Section	S 19	T 29 N	R 03E	5
	S	Τ	R	
4. Lot No:	Recorded Plat:			
5. Private Claims:			_	

201200049477 Filed for Record in MONTMORENCY COUNTY, TERESA WALKER, REGISTER OF DEEDS 01-24-2012 At 09:39:48 am. LAND CORNER 14.00 e 763 1 Fase Liber 763

Liber Pase Instrument 201200049477 763

Register of Deeds Stamp & File Number

2 6 7 10 11 12

I, Carl T, Kiiskila, in a field survey on September, 20 2011 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

B-8 - Center of Section 19, T29N,R03E 1971 Delmer Porter P.S.#15410 set a concrete monument at the intersection of the N-S and E-W 1/4 lines N85°W 5.28' to 13" Poplar N32°E 24.68' to 8" Twin Maple Due East 20.47' 8" Twin Maple Fence corner 8.8' NE

Donald E. Marlatt P.S.#18660 set a 1/2" bar from Porter's witness

5 - CN 1/16 Corner of section 19, T29N,R03E 1971 Delmer Porter P.S.#15410 set a concrete monument per standard BLM procedure.

13

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

B-8 - Center of Section 19, T29N,R03E Found a 1/2" rod with P.S. Cap #18660 fitting the standard B.L.M. instructions for subdivision of a section.

5 - CN 1/16 Corner of section 19, T29N,R03E Found a concrete monument fitting the standard B.L.M. instructions for subdivision of a section.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

ماعد

33981

B-8 - Center of Section 19, T29N,R03E

Replaced 1/2" rod with Stamped 2" dia. alum. cap on 5/8"x 34" rebar

Wit: N16°E 12.92' to set N&T on E side 4" Oak N52°E 9.3' to Fence Corner S89°E 20.01 to set N&T on N side 15"&7" Twin Maple S64°W 4.09' to set N&T on N side 4" Oak N24°W 15.38' to set N&T on E side 7" Oak Set Blue Carsonite post w/location tag 1' North

Surveyor's Michigan License No.:

Ò

Added P.S. cap #33981 to found concrete monument.

5 - CN 1/16 Corner of section 19, T29N,R03E

Wit: N54°E 20.45' to set N&T on NW side 5" W. Pine S36°E 7.99' to set N&T on NE side 4" R. Oak S63"W 34.68' to set N&T on SE side 8"&9" Twin Cherry N26"W 17.62' to set N&T on SW side 8" R. Maple Woven wire fence going East and South, smooth wire fence going North, woven wire fence going Westerly 29' South. Set Blue Carsonite post w/location tag 1' North

OF MICHIGAN CARL KIISKILA LAND SURVEYOR No. 33981 SURVEY

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS JAN. 28, 1971 Revised May 14, 1975 Revised Jan, 1983