LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74 Mich PA 1970

	I	riling Requir	ement of A	CC 74, WIICH	. PA 1970 				
For Corners In: Montmorency (County)	Loca	ted In	Corner Co	de#		*	g ^Q		
1. Public Land Survey	T 30 N	R 02 E	Н9						
Property Controlling in Section	S T T	^_ R R		_					
Miscetlaneous Property in Section	S 27 T 30 N S T		16		Re	egister of Deed	ds Stamp & Fil	e Number	;X.
4. Lot No:	Recorded Plat: _				, АВС	DEF	GHIJ	KLM	
5. Private Claims:			-11		2 -6-	5 4-	3 - 2 -	— 1—	
I, <u>Carl T. Kiiskila</u> , in a field survey on <u>October.20 2010</u> do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:									
NOTE: Not more than be recorded on this ce		e same town	and range,	may	10 30-	32 -33	27 26	25	
A. Daniedaktara da dataa					13	<u> </u>			
A. Description of original monument and accessories and/or subsequent restoration: H-9 – Quarter Corner comm. to sec.'s 22 & 27, T30N,R02E 16 – E 1/16 Cor. comm. to sec.'s 27 & 34, T30N,R02E									
Marlatt, replaced N45°E 42.11' se S20°E 53.54' set S25°W 36.94' se N50°W 67.05' se Cor. is 2' N. of C/N. & 10' W. of old	und 1/2" iron & cap# w/conc. mon. and re t N&T on SE side 24 t N&T on W side 15" et N&T on W side P. et N&T on NE side 2' L E-W gravel rd. & ir d fence to N.	18660 as set emon cap. " R. Pine J.Pine Pole 7" W. Oak I line w/C/L 2-	by D.E.	None			70 2 37 0(
B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:									
H-9 – Quarter Corner comm. to sec.'s 22 & 27, T30N,R02E				16 - E 1/16 Cor. comm. to sec.'s 27 & 34, T30N,R02E					
Found 3 ¼" alum. cap on conc. mon. 1' below grade in E-W paved road per Remon L.C.R.C. – L12, p.379. Cor. is +/- 8' W. of fence line N. and fits 2-track to N. R. Pine witness to NE was gone, so added new witness. Accepted found remon monument as a careful and faithful establishment of the position of the original corner.				Found ½" rebar with no cap. Found rebar is within 0.09' of calculated position. Added ½" P.S. cap# 33981 to iron and accepted as the best available evidence for the position of the corner. Found no other evidence to dispute the location for the corner.					
C. Description of monun	ment for corner and a	iccessories e	stablished to	nernetuate l	ocating the	position of th	A COFFICE		
H-9 – Quarter Corner co							& 34, T30N,	R02E	
Stamped 3 ¼ " dia	ı. alum cap on 4" dia	. conc. monur	ment	½" reb	ar with plast	tic P.S. cap ≱	¢33981		
*S21°W 36.92' to	set N&T on SW side ofd. nail on W side 1 ofd. nail on NW side o set N&T on NE sid	7" J. Pine P. Pole	ak	\$43° \$20° N50°	°E 13.00' to °W 34.20' to °W 6.84' to	set N&T on set N&T on set N&T on	N side 8" R. NE side 8" R E side 8" Oa SW side 7" I cation tag 1'	R.Maple (ol ak R. Maple	blaze) d blaze)
* Witness of prev	rious record.			Get i	Dide Carson	ine post who	cation tag i	North.	
	al TKi	skila		صعب نا) د موسد	OF MICHIC	12	-27-	-10	
Surveyor's Michigan	License No.:	33981		7 510	CARL		· · · ·		
				To the second	KIISKILA LAND SURVEYOR No. 33981	*	6 8 P		
	26			Tree	LAND SUP	2222			
			FORM APPRO	VED BY MICHÌG	AN STATE BO	ARD OF PROF	ESSIONAL SUR	Revised Ma Revised	