

# SURVEY & REMONUMENTATION

JAN 22 2001

Montmorency County Remonumentation

Liber 00012 Page 0416

## SECTION

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

MONTMORENCY  
(County)

Located in BRILEY

Corner Code #

1. Public Land Survey

T 30 N R 2 E B-5

T R

T R

T R

2. Property Controlling  
in Section

S T R

S T R

3. Miscellaneous  
Property in Sec.

S T R

S T R

4. Lot No. , Recorded Plat

5. Private Claims

I, FREDERICK J. KING, in a field survey on MARCH 21, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

B-5 - 1/4 CORNER COMMON TO SECTIONS 7 & 18

June 1840 - Orig Post set by Lewis Clason, D.S. - (1) S28°E-50 lks(33.0')-12" Beech (2) N28°W-38 lks(25.08')-9" Beech Pg. 458

1968 - Conc. Mon set by D.E. Marlatt, PS#18660 - (Surveyor for Scott Eng.) - Set by Sngl Prop - Info from L.G. Beauregard, PS#18654 (3) S19°E-10.42'-5" Cedar (4) S09°W-7.27'-6" Map (5) S56°W-8.23'-5" Cedar - Not Recorded

May 1974 - Act 132 by L.G. Beauregard, PS#18654 (Surveyor for Scott Eng.) - Fnd D.E. Marlatt Mon & Witnesses Rec. L. 1, Pgs. 538 1/2 & 539

June 1985 - Act 132 by D.E. Marlatt, PS#18660 - Fnd Mon (6) N80°E-16.8'-12" Cedar (7) N05°W-19.0'-7" Map - Not Recorded

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

B-5 - 1/4 CORNER COMMON TO SECTIONS 7 & 18

Fnd Rec 4" Conc Mon-Set by D.E. Marlatt, PS#18660 by Sngl Prop In 1968

Witnesses: - Fnd Rec. 6 & 7

THIS CORNER APPROVED BY COUNTY PEER REVIEW ON JULY 18, 2000, AS A CAREFUL AND FAITHFUL ESTABLISHMENT OF THE POSITION OF THE CORNER.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

B-5 - 1/4 CORNER COMMON TO SECTIONS 7 & 18

Placed 3 1/4" Aluminum Montmorency County Re-Mon Cap on Fnd 4" Conc. Mon. Corner is on SW Side Fng Cor Post at N. edge of E-W Pwr Line Clearing. (Wit#6) - N75°E. (R-N80°E) 17.05' (R-16.8') Set S&T - S side 15" Cedar S10°W - 49.42' - Set S&T - E side Pwr Pole #AG356 N80°W - 32.48' - Set S&T - S side 12" Maple (Wit#7) - N05°W - 18.85' (R-19.0') - Set S&T E side 10" Maple

Typical Wit Set = 16-D Spk & Plastic ID Tag #25852

Signed by

Surveyor's Michigan License No. 25852

Date October 30, 2000

STATE OF MICHIGAN  
MONTMORENCY COUNTY  
Recorded & Filed

11-13-2000 13:28:40

TERESA WALKER  
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

A	B	C	D	E	F	G	H	I	J	K	L
1	6	5	4	3	2	1					
2											
3											
4	7	8	9	10	11	12					
5											
6	18	17	16	15	14	13					
7											
8	19	20	21	22	23	24					
9											
10	30	29	28	27	26	25					
11											
12	31	32	33	34	35	36					
13											

APPROVED BY  
PEER GROUP

JUL 18 00

L.G.B.

