

SURVEY & REMONUMENTATION

JAN 22 2001

Montmorency County Remonumentation

Liber 00012 Page 0423

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

MONTMORENCY
(County)

Located in: BRILEY Corner Code #

1. Public Land Survey

T 30NR 2E D=7
T R
T R
T R

2. Property Controlling
in Section

S T R
S T R

3. Miscellaneous
Property in Sec.

S T R
S T R

STATE OF MICHIGAN
MONTMORENCY COUNTY
Recorded & Filed

11-13-2000 13:32:58

TERESA WALKER
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat

5. Private Claims

I, FREDERICK J. KING, in a field survey on APRIL 3, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

1	A	B	C	D	E	F	G	H	I	J	K	L
2		6		5		4		3		2		1
3												
4		7		8		9		10		11		12
5												
6		18		17		16		15		14		13
7												
8		19		20		21		22		23		24
9												
10		30		29		28		27		26		25
11												
12		31		32		33		34		35		36
13												

A. Description of original monument and accessories and/or subsequent restoration:

D-7 - 1/4 CORNER COMMON TO SECTIONS 17 & 20

June 1840 - Orig Post set by Lewis Clason, DS - Marked 10" Cedar for Cor - No Witnesses - Pg. 456
Sept 1941 - Notes of Frank Smith, PS#754 - Fnd 10" Cedar Marked 1/4 S 1730W 2E. This cedar is 50' N of trail and a stral line between Sec. Corners would be 66' S. The 17 faced Sec 20. I doubt that this is the Govmt 1/4 Post into obtained from L.G. Beauregard, PS#18654 - Set 2 1/2" Conc Mon - (1)N45°E-50.0'-4" Conc Mkr (2)S45°W-50.0'-4" Conc Mon.
Nov. 1987 - LCRC by L.G.Beauregard, PS#18654 (Surveyor for Scott Eng) - Rec L.1, Pg.406 - Fnd 4" Conc Mon - Set by L. Briley & P.Beltz in 1941 (#1)N45°E-50.0'-6" Conc Mon (#2)S45°W-50.0'-6" Conc Mon-(#3)N03°W-14.17'-8" Ceda (#4)S30°E-7.02'-6"Cedar-(#5)S45°E-20.06'-8"Cedar

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

D-7 - 1/4 CORNER COMMON TO SECTIONS 17 & 20

Fnd 4" Conc Mon (Rec as 2 1/2" & 4")
Witnesses - Fnd Rec. 1, 2, 3, 4



THIS CORNER APPROVED BY COUNTY PEER REVIEW ON JULY 18, 2000, AS THE BEST AVAILABLE EVIDENCE OF THE POSITION OF THE ORIGINAL CORNER.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

D-7 - 1/4 CORNER COMMON TO SECTIONS 17 & 20

Placed 3 1/4" Aluminum Montmorency County Re-Mon Cap on Fnd 4" Conc Mon - Set Treated 2"x4" Alongside.
(Wit#3) - N03°W - 14.17' - Set S&T above fnd Spk - W side 10" Cedar
(Wit#1) - N45°E - 50.03' (R-50.0') - Fnd Rec 6" Conc Mon * N75°E - 18.63' - Set S&T - NW side 12" Cedar
(Wit#4) - S30°E - 7.05' (R-7.02') - Set S&T above fnd Spk - W side 8" Cedar
(Wit#2) - S45°W - 50.07' (R-50.0') - Fnd Rec 6" Conc Mon * S80°W - 3.64' - Set S&T above Fnd Spk - S side 10" Cedar

APPROVED BY
PEER GROUP

Typical Wit Set = 16-D Spk & Plastic ID Tag #25852

Signed by

Surveyor's Michigan License No. 25852

Date October 30, 2000

JUL 18 00

L & B.