REMONUMENTATION

JAN 2 2 2001

Montmorency County Remonumentation

SECTION

For corners in

Land Corner Recordation Certificate
Filing Requirement of Act 74, Mich. P.A. 1970

MONTMORENCY Located In: BRILEY TWP.	STATE OF MICHIGAN MONTMORENCY COUNTY Recorded & Filed 12-05-2000 10:06:39 TERESA WALKER REGISTER OF DEEDS Register of Deeds Stamp & File Number
4. Lot No, Recorded Plat	
5. Private Claims	A B C D E F G H I J K L
I, DONALD E MARLATT, in a field survey on MAY X†9 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:	2
NOTE: Not more than 2 comers, all in the same town and range, may be recorded	9 20 21 22 23 24
ON this certificate. OUT OF PLACE-COUNTY ROAD COMMISSION NOTES:1941 CONC. MONUMENT, WIT. 4' CONC. MARKER N45°E 50'(F.S. TVP.) 4' CONC. MARKER S45°W 50'(F.S. TVP.)	10 30 29 28 27 26 25 11 12 31 32 33 34 35 36
A. Description of original monument and accessories and/or subsequent restoration: E-3 CORNER COMMON TO SECTIONS 4-5-8 \$ 9. G.L.O. COR. WAS SET BY LEWIS CLASON IN APRIL 1840. BEECH 12" NE FRANK SMITH P.S. #754 NOTES: G. STEVENS ON MAY 24, 1935 FOUND CELM 4" N26°40'E 53.75', ELM 4" S27°30'E 13.1'. G.G. SLATTERY P.E. MSHD SURVEY CREW CHIEF IN DEC. 1967 FOUND COMMIT ABOVE GROUND IN FENCE CORNER EAST-WEST & SOUTH. N45°E 50' COMMIT OF CONC. MONUMENT, S20°E 8.38' 9"MAPLE, N55°W 27.44' 8"MAPLE. COUNTY ROAD COMMISSION NOTES CALLED FOR A MONUMENT. N45°E 50' MONUMENT(NO DATE).	ONE B & P, PLACED CEDAR STAKE. ONC. MONUMENT WITH 1/2" PIN, ONC. MONUMENT, S45°W 50' MONUMENT, S45°W 50'
B. Description of corner evidence found and/or method applied in restoring or reestablishing corne E-3 CORNER COMMON TO SECTIONS 4-5-8 £ 9. FOUND CONC. MONUMENT IN FENCE CORNER EAST-WEST £ SOUTH. N45°E 50' CONC. MONUMENT R. (F.S. TYP.) S45°W 50' CONC. MONUMENT R. (F.S. TYP.) S23°E 7.8' 12"BEECH N53°W 27.5' 16"MAPLE R.	APPROVED BY PEER CROUP UL 1 8 00 J. L.B.
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner and accessories established to perpetuate locating the position of the corner common to sections 4-5-8 & 9. PLACED REMON. CAP ON EXISTING CONC. MONUMENT. N45°E 50' CONC. MONUMENT S45°W 50' CONC. MONUMENT S23°E 7.80' 12"BEECH N53°W 27.50' 16"MAPLE WITNESSES MARKED WITH 40 PENNY SPIKES AND P.S. TAGS#18660. APPROVED BY PEER GROUP ON JULEY 18, 2000 AS A PERPETUATION OF THE	DONALD E MARLAIT SURVEYOR NO. 18660
Signed by <u>Janala E Marlatt</u> Date 12/ Surveyor's Michigan License No. 18660	4/2000