

Montmorency County Remonumentation

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN
MONTMORENCY COUNTY
Recorded & Filed

For corners in

Montmorency (County)	Located In: Rust Township	Corner Code ##
1. Public Land Survey	T 30N R 4E	B-1
	T R	
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	

09-27-1996 13:27:21

A. PANGAN-MCELROY
REGISTER OF DEEDS

Liber 00012 Page 0202

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat
5. Private Claims

I, Larry G. Beauregard, in a field survey on June, 1996, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

B-1 North 1/4 Corner Section 6

No corner set on original survey.

1982 - Kenneth J. Ostling RLS # 10068 DNR surveyor set 5/8" x 36" Iron Bar by proportionate measurement Bet.

Sec. corners at Latitude of the correction line. Then filed L.C.R.C. Rec. L. 1, P. 330 wit's marked:

(S 70° W 18.2' 7" Cedar) (S 55° W 60.9' 6" Cedar).

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 5/8" x 36" bar without cap 1.6' feet East of DNR std. cor. for Sec 31 & 36, T 31N. R 3 & 4E.

Placed 3/4" x 36" pipe and Mont. Co. re-mon cap over 5/8" bar and drove down too 1' foot above ground.

SURVEY &
REMONUMENTATION

MAY 22 1997

COMMISSION

APPROVED BY
PEER GROUP

JUN 17 96

LSB

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

North 1/4 Corner Section 6

3/4" x 36" pipe and Mont. Co. re-mon cap over 5/8" bar. Accepted as a careful and faithful establishment of the position of the corner. Approved by the Peer Group on June 7, 1996.

South 19.70' 3" Balsam

S 40° E 39.60' Tw. 6" Cedars

S 65° W 19.73' 11" Cedar. (R) S 70° W 18.2'

N 65° E 33.60' 8" Birch

Placed 60d penny spike, P.S. tag # 48654 & blaze. (typ.)



Signed by Larry G. Beauregard
Surveyor's Michigan License No. 18654

Date 9-24-96