

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in  
WORTHRENCY  
(County)

Located In:

Corner Code ≠

1. Public Land Survey

T 32N R 4E

A-7

T \_\_\_\_\_ R \_\_\_\_\_

T \_\_\_\_\_ R \_\_\_\_\_

T \_\_\_\_\_ R \_\_\_\_\_

2. Property Controlling  
in Section

S 18 T \_\_\_\_\_ R \_\_\_\_\_

11, 12, 15

S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_

3. Miscellaneous  
Property in Sec.

S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_

S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_

5. Private Claims \_\_\_\_\_

I, C. T. KIISKILA, in a field survey on OCTOBER 25, 19 94,  
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned  
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the  
current manual of survey instructions of the United States Department of the Interior, Bureau of Land  
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5  
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a  
Court of Law; established, re-established, monumented, re-monumented, recovered, found as  
expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded  
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

A-7

11

12

(NO EVIDENCE OF G.L.O. CORNER, B.T.'S, LINE TREES & TOPOGRAPHY,  
AS CALLED OUT IN THE G.L.O. LINE NOTES; UNLESS NOTED IN ITEM "B"  
BELOW.)

|    | A  | B  | C  | D  | E  | F  | G | H | I | J | K | L | M |
|----|----|----|----|----|----|----|---|---|---|---|---|---|---|
| 2  | 6  | 5  | 4  | 3  | 2  | 1  |   |   |   |   |   |   |   |
| 3  |    |    |    |    |    |    |   |   |   |   |   |   |   |
| 4  | 7  | 8  | 9  | 10 | 11 | 12 |   |   |   |   |   |   |   |
| 5  |    |    |    |    |    |    |   |   |   |   |   |   |   |
| 6  | 18 | 17 | 16 | 15 | 14 | 13 |   |   |   |   |   |   |   |
| 7  | •  | •  |    |    |    |    |   |   |   |   |   |   |   |
| 8  | 19 | 20 | 21 | 22 | 23 | 24 |   |   |   |   |   |   |   |
| 9  |    |    |    |    |    |    |   |   |   |   |   |   |   |
| 10 | 30 | 29 | 28 | 27 | 26 | 25 |   |   |   |   |   |   |   |
| 11 |    |    |    |    |    |    |   |   |   |   |   |   |   |
| 12 | 31 | 32 | 33 | 34 | 35 | 36 |   |   |   |   |   |   |   |
| 13 |    |    |    |    |    |    |   |   |   |   |   |   |   |



B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

A-7

11

12

15

REESTAB'D SW COR S-18 AT  
INTERSECTION OF LINES ACROSS  
FD NW COR S-18 & FD SE COR  
S-13 (T32N-R3E) AND FD PIPE  
(349' E'LY) & FD SE COR S-18.  
N-S SMOOTH WIRE IS 4.5' WEST.  
FD A 3/4" PINCH PIPE;  
S02°32'E, 75.83'

ESTABLISHED THE CTR OF THE  
FRACTIONAL SW 1/4 S-18 PER  
STANDARD BLM INSTRUCTIONS.  
N-S TRAIL IS 30' WEST.

ESTABLISHED SE COR OF NE 1/4  
OF SW 1/4 S-18 PER STANDARD  
BLM INSTRUCTIONS. A SINGLE  
STRAND OF SMOOTH WIRE ON TREES  
IS 13'+/- SOUTH.  
FD OLD 1 1/2" PIPE, LEANING,  
IS S84 41'W, 210.3'.

ESTABLISHED SE COR OF FRL.  
SW 1/4 OF FRL SW 1/4 S-18  
PRORATED TO U.S. GLO RUN OUT  
BETWEEN S 1/4 & SW COR'S OF  
S-18.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A-7

11

12

15

SET BNR MON & CED POST.

DROVE 5/8" X 34" REROD W/PS  
CAP. SET CED POST W/LDC TAG.

DROVE 5/8" X 34" REROD W/PS  
CAP. SET CED POST W/LDC TAG.

SET 5/8" X 32" REROD W/CAP &  
CEDAR POST.

12" MAPLE N26°W 10.51'  
9" CEDAR S86°W 8.42'  
4" CEDAR S24°E 15.51'  
4" CEDAR S84°E 25.36'  
SE COR S13, T32N-R3E FD 1 1/4"  
IR PIPE N01°22'23"W 306.43'

7" BEECH N35°W 32.71'  
10" MAPLE N60°E 33.70'  
4" MAPLE S55°E 16.51'  
12" MAPLE S55°W 15.33'

8" MAPLE (CLP2) N30°W 22.33'  
10" CEDAR N50°E 70.63'  
5" MAPLE S05°W 29.03'  
14" TW MAPLE S70°W 30.87'

5" BALSAM S37°W 7.02'  
12" W PINE N49°W 47.32'  
10-13" TW MAPLE N40°E 21.75'  
5" TRPL MAPLE S68°E 55.31'  
FD 2" D.D.  
PIPE S86°27'W 328.62'

Signed by

Carl T. Kiiskila

Date

2-27-97

Surveyor's Michigan License No.

33981