

SURVEY &
REMONUMENTATION

MAR 19 1998

1997 Newaygo County Remonumentation Project

NEWAYGO COUNTY
REGISTER OF DEEDS
LINDA M. BROWN

SECTION

LAND CORNER RECORDATION CERTIFICATE
FILING REQUIREMENT of Act 74, Mich. P.A. 1970

'98 MAR 6 PM 12 36

For corners in
Newaygo
(County)

Located in:

Corner Code #

Linda M. Brown

1. Public Land Survey

T 14N R 13W

C-4

T R

T R

T R

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous
Property in Sec.

S T R

S T R

4. Lot No. , Recorded Plat

5. Private Claims

VOL. 2

103

Register of Deeds Stamp & File Number

I, Norman L. Ochs, in a field survey on November 6, 1997,
do hereby certify that under requirements of P. A. 74, Michigan P.A. of 1970, the corner
points mentioned in lines 1 and 2 above were in conformance with regulations and rules
therefore as required in the current manual of survey instructions of the United States
Department of the Interior, Bureau of Land Management or by a decree of a Court of
Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in
conformance with the rules of the Michigan Board of Land Surveyors or by a
Decree of a Court of Law; established, re-established, monumented, re-monumented,
recovered, found as expressed below:

**Note: Not more than 4 corners, all in the same town and range, may be
recorded on this certificate.**

East One Quarter Corner, Section 7, Lincoln Township, Newaygo County, Michigan.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

G.L.O. Milton Nye Resurvey 1856
5" Beech N61½°E 35 Links (23.10') #1
11" Beech S16°W 31 Links (20.46') #2

William M. Jacques (County Surveyor)
Book B Pages 14 and 15 December 9, 1904
Witness tree stump good

Delos G. Anderson (County Surveyor)
Book A Pages 201 and 202 April 15, 1897
14" Pine Stump S60°W 38 Links (25.08') #3
18" Pine Stump S18°E 34 Links (22.44') #4

George W. Clark Jr. P.E. and R.L.S. #6728
(John Kistler and Associates)
August 25, 1972 LCRC #54
Found 1" Pinch Pipe in old fences East - West - South
24" Oak S38°W 38.17' #5
6" White Pine N74°W 26.30' #6
6" White Pine N10°E 10.08' #7

**B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR
REESTABLISHING CORNER:**

Found 1" Pinch Pipe at approximate intersection of fence strands on ground going West and South and East. The condition
of the recorded witnesses are: #1 thru #4 gone, #5 (stump), #6 leaning, #7 good condition.

**C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING
THE POSITION OF THE CORNER:**

Removed 1" Pinch Pipe and set 4" diameter Harrison cast iron monument 30" long marked "County Surveyor" as a
substantial marker for the section corner and is accepted as a careful and faithful reestablishment of the original corner.

24" Oak Stump S42°W 37.50' to face. #5
10" White Pine N75°W 25.45' to face. #6
10" White Pine N14°E 9.98' Set spike and brass washer in West side of tree. #7
8" Maple S42°W 15.32' Set spike and brass washer in Southeast side of tree.
12" White Pine N72°E 26.27' Set spike and brass washer in North side of tree.
12" White Pine N45°W 12.0' Set spike and brass washer in Southwest side of tree.

Signed by Norman L. Ochs

Date November 10, 1997

Surveyor's Michigan License No. 22439

Form approved by Michigan State Board of Land Surveyors, Jan 28, 1971
Revised May 14, 1975
Revised Jan., 1983

Approved by Peer Review Group on November 11, 1997
Norman L. Ochs, County Representative.

N.L.O.

