MAR 1 3 2000

## 1999 Newaygo County Remonumentation Project

NEWAYGO COUNTY REGISTER OF DEEDS HYOR H. EROWN

SECT	NOI
------	-----

LAND CORNER RECORDATION CERTIFICATE '00 FEB 28 PM 1 18 FILING REQUIREMENT of Act 74, Mich. P.A. 1970

	, ,2,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,			Ain.	ans Y	n. 60	www	
For corners in Newaygo (County)	Located in:	Corner Code#		Suc		,, <u> </u>		
1. Public Land Survey	T <u>16N</u> R <u>11W</u> T R T R T R	1-2	i	VOL.	2		37	′3
Property Controlling     in Section     Miscellaneous     Property in Sec.	STR STR STR STR		egister o	f Deeds	Stamp	& File	Number	<b></b>
4. Lot No, Record 5. Private Claims, Record 6. Private Claims, Record 7. Private Claims, Record 8. Private Claims	corners, all in the same to	, 19 99 , A, of 1970, the corner regulations and rules of the United States decree of a Court of d 5 above were in Surveyors or by a ted, re-monumented,	2 - 6 3 - 4 4 - 7 5 - 18 7 - 18 9 - 10 - 3 11 - 1	9 - 20 -	- 4 - 9 - 16 - 21 - 28	10 - 15 - 22 27 27	J K L M 2 - 1 - 11 - 12 - 14 - 13 - 123 - 24 - 26 - 25 - 35 - 36 -	
West One Quarter Corner,	Section 2, Barton Township, N	lewaygo County, Michigan.	13					
A DESCRIPTION OF O	RIGINAL MONUMENT AN	ID ACCESSORIES AND/	OR SUB	SEQUE	NT RE	STORA	TION:	

G.L.O. Milton Nye 1856 Resurvey 14" Beech S60°W 19 Links (12.54')#1 10" Sugar N38°E 43 Links (28.38')#2

Newaygo County Road Commission Sheet Fence Post West 33.0' #5 Fence Post East 29.3' #6

Robert L. Wetherell R.L.S. #24624 March 29, 1996 Recorded in Liber 365, Page 5477 Power Pole N85°W 67.32' #8 7" Elm \$33°E 47.60' #12 Clump Apple \$76°E 37.68' #13 5" Elm N40°E 54.64' #14

Lyle S. Shepherd R.L.S. #503 Book B, Page's 72 and 73 November 19, 1915 Book 96, Page 13 and Witness Book Number 1, Page 132 Stone Corner 16" Maple N51°W 66 Links (43.56')#3 Large Granite Bolder Marked "X" S14°E 81 Links (53.46')#4

James J. Keller R.L.S. #10693 August 9, 1989 Recorded in Liber 349, Page 1596 Found Railroad Spike two inches under blacktop 28" Maple N06°W 161.97' #7 Power Pole N88°W 66.94' #8 Fence Post S88°W 35.17' #9 6" Basswood S15°E 81.35' #10 Fence Post S87°E 30.85' #6 Concrete Post Southwest Face S64°E 34.7' #11

## B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:

Found Railroad Spike in centerline of the North and South bituminous road and on tree line going East and on fence line going West. The condition of the recorded witnesses are: #1 thru #6 gone, #7 and #8 good condition, #9 post leaning, #10 gone, #11 flat, #12 thru #14 good condition.

## C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

Removed Railroad Spike and set a 23/4" diameter Harrison cast iron monument 18" long marked "County Survey" in monument box as a substantial marker for the quarter corner and is accepted as a careful and faithful reestablishment of the position of the original corner.

32" Maple N15°W 161.95' Four Power Pole West 66.93' Found Fence Post (leaning) S80°W 3 10" Elm S40°E 47.58' Found s Clump Apple Trees S85°E 37. 8" Elm N33°E 54.63' Found sp	d P.K. in North side of pole 35.85' Found spike in South spike in Southwest side of to 68' Found spike in South si	, #8 least side of pos ree. #12 ide of tree. #13	t. # <del>9</del>
Signed by Norman L. Ochs		Date	October 22, 1999
Norman L. Ochs			

November 30, 1999

Signed by 1/9man	T. OR	hs	Date	October 22, 1999	10
Norman L. Ochs					and actional Company
Surveyor's Michigan License No.	22439		Form approve	ed by Michigan State Bo	eard of Land Surveyors, Ja Revised Ma

n 28, 1971 Revised May 14, 1975

Revised Jan., 1983

NORMAN L. OCHS LAND SURVEYOR

22439

LAND

Norman L. Ochs, County Representative.

Approved by Peer Review Group on