

1994 NEWAYGO COUNTY REMONUMENTATION PROJECT

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

VOL 001 PAGE 144

For corners in
Newaygo

(County)

Located In:

Corner Code #

1. Public Land Survey

T 16N R 12W

C-5

T R

T R

T R

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous

S T R

Property in Sec.

S T R

4. Lot No. , Recorded Plat

5. Private Claims

NEWAYGO COUNTY
REGISTER OF DEEDS
MARLENE TOOGOOD

'95 MAR 14 PM 3 59

Marlene Toogood

Register of Deeds Stamp & File Number

I, Norman L. Ochs, in a field survey on September 28, 1994

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

NW Corner, Sec. 17, Home Twp., Newaygo County MI

A. Description of original monument and accessories and/or subsequent restoration:

GLO Milton Nye 1856

20" W. Oak N58-1/2°E 15 lks (9.90') #1

15" W. Oak S40°W 10 lks (6.60') #2

1939 J. Weber (U.S.F.S.)

Wood stake in intersection

of roads N-S & E-W

Post N47-1/2°W 45 lks (29.7') #3

7-20-73 Gerald J. Gray RLS #17741

Measured 2794.39 ft. from the NW cor. to the W-1/4 cor. of Sec. 17 See survey

recorded Series E 8389

3-27-74 Paul Paquette RLS #16938

Set 5" x 5" x 36" conc. mon.

16" B. Oak N25°E 58.54' #4

14" B. Oak S42°W 31.83' #5

16" R. Oak N52°W 61.17' #6

-OVER-

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

In September 1994, I, Norman L. Ochs, found 5" sq. x 36" conc. monument and measured 2795.17 ft. from the W-1/4 cor. to the NW. cor.

Condition of recorded witnesses is: #1 thru #3 gone, #4 thru #7 good condition.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:


Accepted 5" sq. x 36" conc. mon as a substantial marker for the section corner and is accepted as a careful and faithful reestablishment of the original corner.

22" R. Oak N23°E 58.55' Spike on West side of tree. #4

22" R. Oak S42°W 31.75' Spike on East side of tree. #5

26" R. Oak N55°W 61.08' Spike on East side of tree #6.

P.Pole S48°E 35.66' Spike on SW side of pole #7.



Signed by Norman L. Ochs

Date October 18, 1994

Surveyor's Michigan License No. 22439

Approved by Peer Review Group on October 19, 1994.

Norman L. Ochs, County Representative

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1993

SURVEY &
REMONUMENTATION

DEC 07 2000

SECTION

A cont.

6/19/74 Robert A. Griffin RLS #13584

Fnd. 5" sq. x 36" conc. mon w/cap #16938

Recorded in LCRC #323

19" R. Oak N23°E 58.65' #4

P.Pole S48°E 35.63' #7

15" R. Oak S42°W 31.85' #5

17" R. Oak N55°W 61.15' #6

Measured 2796.94 ft. from the NE cor. to the E-1/4 cor. of Section 18.

10/16/90 Newaygo Eng. & Survey Co.

Fnd. conc. monument

16" B. Oak N25°E 58.59' #4

14" B. Oak S42°W 31.77' #5

16" R. Oak N52°W 61.14' #6

P.Pole S48°E 35.64' #7

Measured 2795.96 ft. from the NE cor. to the E-1/4 cor. of Section 18.

Clinton E. Cole R.L.S. #17615

December 8, 1977

See File No. 2841-77

Measured 2796.94 feet from the N.E. Cor. to the E. 1/4 Cor. of SEc. 18.

SURVEY &
REMONUMENTATION

DEC 07 2000

SECTION