## LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In: Ogernaw (County)	Located In Corner Code #	*
Public Land Survey     Property Controlling	T R	
in Section  3. Miscellaneous Property in Section	S 6 T 21N R 3E 11 S T R	
4. Lot No:	S T R	Register of Deeds Stamp & File Number
requirements of PA 74, Mi and 2 above were in confo	d survey on February 7, 2006 do hereby state that under ichigan PA of 1970, the corner points mentioned in lines 1 promance with regulations and rules therefore as required in the instructions of the United States Department of the	4 7 7 5 9 10 11 12 12
Interior, Bureau of Land Ma corner points mentioned in of the Michigan Board o established, re-established	lines 3, 4 and 5 above were in conformance with the rules of Land Surveyors or by a Decree of a Court of Law; monumented, recovered, found as expressed below:	6 -18 -17 -16 -18 -14 -13 -1

A. Description of original monument and accessories and/or subsequent restoration: 11-This corner position was not established during the original government survey.

- B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:
- 11- Established the Southeast corner of the Northwest quarter of the Southwest quarter of section 6 as per B.L.M. instructions for the subdivision of a section.

be recorded on this certificate.

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- 11- Set a 5/8" x 32" rerod with P.S. cap #33981

Wit: 13" Oak	N09°W	34.70'	
5" W. Pine	N88°E	19.85'	
7" W. Pine	S06°E	18.22'	
8" W. Pine	S84°W	34.881	
4" Pipe	N53°W	127.65'	
Carsonite Pos	st North	1'±	

Signed by:

CAND SURVE Date:

Surveyor's Michigan License No.: 33981 KIISKILA LAND