

# LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:

Ogemaw

(County)

Located In

Corner Code #

1. Public Land Survey	T	23N	R	2E	G-10
	T	23N	R	2E	E-10
2. Property Controlling in Section	S		T		
	S		T		
3. Miscellaneous Property in Section	S		T		
	S		T		

4. Lot No: Recorded Plat:

5. Private Claims:

I, Carl T. Kiiskila, in a field survey on October 29, 2008 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

**NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.**

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	8			5			4		3		2		1
3													
4	7			6			9		10		11		12
5													
6	18			17			16		15		14		13
7													
8	19			20			21		22		23		24
9													
10	30			29			28		27		26		25
11													
12	31			32			33		34		35		36
13													

A. Description of original monument and accessories and/or subsequent restoration:

G-10 GLO – James H. Mullett D.S. - 1846

Set Qr. Section Post

Wit: B. Oak 6 S25°E 11 links

B. Oak 4 N36°W 33 links

E-10 GLO – J.H. Mullett D.S.–1846- Set Post Qr. Sec. Post

Wit: Black Oak 6" N33°W 2.62 chains

Aspen 4" S41°E 1.10 chains

Certificate of Survey-L.1,p.205-L.Cavanagh

P.S.#17614- Found 5/8" Iron for corner.

Wit: 8" W. Pine N30°W 42.32'

7" R. Pine East 24.15'



B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

G-10 Found no conclusive evidence of the position of the original corner. Set stamped 4" Aluminum cap on 1"x3' galvanized pipe per standard BLM procedure and is accepted as a careful and faithful reestablishment of the position of the original corner.

E-10 Found 5/8" rebar +/-2' W of N-S C/L seasonal road. Added P.S. cap#33981 to found iron. Accepted found iron as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G-10 Stamped 4" Aluminum cap on 1"x3' galvanized pipe with several 6"-8" field stones around monument.

Wit: N14°W 35.05' to set N&T on W side 13" White Pine

N74°E 9.91' to set N&T on N side 8" Red Oak

S14°E 22.16' to set N&T on W side 6" White Oak

S62°W 21.98' to set N&T on S side 9" Red Oak

Set Blue Carsonite Post with Loc. Tag 1' North

E-10 Added P.S. cap#33981 to found 5/8" rebar.

Wit: S42°E 48.13' to set N&T on NE side 11" Maple

S84°E 24.48' to fd. nail on N side 9" R. Pine

N17°W 42.33' to set N&T on NW side 10" W. Pine

N41°E 39.06' to fd. nail on NW side 18" R. Oak

S69°W 54.14' to fd. nail on N side 16" R. Pine

Set Blue Carsonite with Loc. Tag 33' East

Signed by:

Carl T. Kiiskila

Date:

6-17-09

Surveyor's Michigan License No.:

33981