## LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

|   | and the quite of the   |  |   |
|---|--|--|---|
| For Corners In:<br>Otsego   | Located In Corner C  | 1. 44  |   |
| (County)  | Located In Corner C  | De #   |   |
| 1. Public Land Survey   | T <u>29N</u> R 1W <u>F-6</u>   |  |   |
| Property Controlling in Section     .      Miscellaneous Property in Section  | S 16 T 29N R 1W 8<br>S T R   | <u>~</u> ~   |   |
|   | S T R  | Register   | of Deeds Stamp & File Number  |
| 4. Lot No:  | Recorded Plat:   | A B C D  | EFGHIJKLM   |
| 5. Private Claims:  |  | 2 6 5  |   |
| requirements of PA /4, Mic<br>and 2 above were in confo<br>the current manual of sur<br>Interior, Bureau of Land Ma<br>corner points mentioned in<br>of the Michigan Board of                       | I survey on August 30, 2007 do hereby state the chigan PA of 1970, the corner points mentioned in transce with regulations and rules therefore as receivey instructions of the United States Department nagement or by a decree of a Court of Law and/or lines 3, 4 and 5 above were in conformance with the Land Surveyors or by a Decree of a Court monumented, recovered, found as expressed below. | ines 1 4 7 8 ired in of the nat the e rules 7  | 9 10 11 12 15 14 13 21 22 23 24 24  |
| NOTE: Not more than 2 corners, all in the same town and range, may  |  | 1ay 9 10 30 29   | 28 27 22  |
| be recorded on this cer   | rtificate.   | 11   | 28 27 25 25   |
|   |  | 12 3 32  | 33 34 35 36   |
| A Description of original   | monument and account in  | 13   | <del>* · · · · · · · · · · · · · · · · · · ·</del>  |
| A. Description of original monument and accessories and/or subsequent restoration:  F-6 This corner was not established during the original  8- This corner was not established during the original |  |  |   |
|   |  |  |   |
| B. Description of corner of F-6 Established center North- South and Eas   | evidence found and/or method applies in restor<br>of section 16 at the intersection of the<br>t-West ¼ lines.  | ing or re-establishing corner:<br>3- Established the Northwes<br>of the Southwest quarter of<br>instructions for the subdivis                              | section 16 as per B.L.M.  |
| F-6 Set 5/8" X 32" iron wi<br>Wit: Set nail and tag in the<br>Set nail and tag in the   | ne West side 9" Jack Pine N62°W 67.59' ne West side 9" Jack Pine N33°E 40.94' ne West side 9" Jack Pine S26°E 25.27' building S54°W 80.65'   | <ul> <li>Set 5/8" X 32" iron with P.S.</li> <li>Wit: Set nail and tag in the Sou<br/>Set nail and tag in the We<br/>Set nail and tag in the Sou</li> </ul> | cap #33981<br>uth side 4" Jack Pine N72°W 8.73'<br>est side 3" Cherry S15°E 17.95<br>uth side 13" Jack Pine N45°E 38.51<br>uth side 13" Jack Pine N72°E 54.24 |
|   |  |  | SERVICE MICH  |
|   |  |  | SANTE OF MICHIGAN   |

Signed by:

Surveyor's Michigan License No.:

33981

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS JAN. 28, 1971
Revised May 14, 1975
Revised Jan. 1983
Revised Oct. 1995

Date:

LAND